

31 AUG 1953

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 26th August 1953 When handed in at Local Office 27th August 1953 Port of Gothenburg
No. in Reg. Book 23441 Survey held at Marstrand, Rönäng, Gothenburg Date, First Survey 16th June Last Survey 19th August 1953
(No. of Visits 5)
Built at Goole By whom Goole Shipbuilding & Repairing When 1944 - 3
Owners Lennart B. Kristensson and others Owners' Address ---
(If not already recorded in Appendix to Register Book)
Managers --- Port belonging to Rönäng
On Slipway
Name of Slipway A+B. Marstrands
Destined Voyage Mek. Verkstad

ried Afloat or in Dry Dock? and Afloat Name of Ship Slipway A+B. Marstrands
Bor DBa feet; uE & B feet; f feet
capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

st Report, No. 19236 Port 807

ical Surveys, when held, must be reported in detail and serially in the terms of the Rules and Items remaining to complete
e Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations
id subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to
her causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the
placement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form.
ate also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he
offered his services for this purpose and to whom and why they were declined Offered to

Owners, but not required

Was a damage report made by anyone else? if so, by whom? Yes, Underwr. surveyor

PAIRS, OR EXAMINATION AS PER RULE, FOR DAMAGE,

the cause of which was not stated, and

stated to have been caused by contact with the m.t. "B.T. IX" in May, 1953.

r SPECIAL SURVEY (Due 4.53. Ship 9 years old), and ENDORSEMENTS.

W done:

Vessel placed on slipway, shell plating, sternframe and rudder cleaned, examined, found or placed in order,
nd re-coated. Ship undocked on the 17th June, 1953.

P.T.O.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...	1							
Removed and Fairred or Repaired								
Fairred or Repaired in place ...	See report							

PRESENT CONDITION OF THE	Good	Bulkheads	Good	Engine Room Skylights	Good	Copper, or Y.M.	---
Decks	Good	Ceiling	Good	Coal Bunkers, Openings, Covers, &c.	---	(State if on Felt.)	---
Caulking of Decks	Good	Cement or asphalt	Good	Oil Bunkers	Good	When fitted, Month	---
Coamings	Good	Rudder	Good	Scuppers	Good	Boats	Good
Beams & Fastenings	Good	Steering gear and its connections	Good	Cargo Hatchways	Good	Masts, Yards, &c.	Good
Outside Plating	Good	Windlass	Good	Hatches	Good	Condition, how ascertained	Examined
" " In way of sidelights	Good	Have pumps been examined and found efficient?	Yes	Planking	---	(State if wedges removed.)	---
Frames	Good	Have Sluice Valves been examined and found efficient?	None	Caulking	---	Equipment letter	C 16/16
Reverse Frames	Good	Have Watertight Doors been examined and found efficient?	Yes	Treenails	---	Anchors, No. of	3 B., 1 S.
Longitudinals	Good	Have Ventilators and their Coamings been examined and found efficient?	Yes	Breasthooks & Stemson	---	Cables (State if now ranged)	Yes
Transverses	Good	Air and Sounding Pipes	Good	Transoms, Pointers & Crutches	---	length 180 f. mean diamr.	1"
Floors	Good	Doubling Plates under Sounding Pipes	Good	Timbers of Frame at openings	---	(on board.)	---
Keelsons	Good			" " at other places	---	Rule length 165 f. size	1"
Stringers	Good			Stringers, Clamps & Shelves	---	Chain Locker	Good
Inner Bottom Plating	Good			Salting	---	Hawsers & Warps	Good
Have the Tanks been examined internally?	Yes			State if examined	---	Standing Rigging	Good
Have the Tanks been tested?	Yes				---	Sails	---

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

This vessel is in good condition and eligible, in our opinion, to remain as classed with fresh docking date
Marstrand 6.53 and notation of ssGot.-8.53, subject to the port side bower anchor being renewed at the earliest opportunity, Endorsement: A few keel, bottom and side shell plates (port and starboard) indented.

Survey Fee (per Section 23) Kr. 380:00 Fees applied for, 27/8 10.53
Special Damage or Repair Fee (if any) Kr. :75:00 Received by me, 10.53
Travelling Expenses (if chargeable) Kr. 1:18:55
Second Surveyor's Fee (if any) £ : :
Committee's Minute 6.10.53
Character Assigned 6.53 Got subject (with endorsements)
as Got. 8.53 MBS* 8.53

Surveyor of Lloyd's Register of Shipping.

© 2021

Lloyd's Register

Foundation

011657-011664-0070

Damage No. 1:

1 plate on the starboard bow cropped and partly renewed.

Damage No. 2:

Port side bower anchor specially examined. The flew found broken.

Port side bower anchor specially examined. The
The Owners stated that a new anchor is ordered and will be delivered at the earliest opportunity.
tunity.

On completion the shell plating was satisfactorily hose tested as necessary.

Periodical Special Survey (Due 4.53. Ship 9 years old):

Now done:

Now done:
Ship placed on slipway, shell plating, sternframe and rudder cleaned, examined, found or placed in order, and re-coated. Ship undocked on the 17th June, 1953.

Examined:

Examined:
Poop 'tween decks, fore and after peak spaces, engine space, under engines, pump room, plating in way of sidelights, decks, hatchways, covers, supports, anchors, chain cables, chain locker, masts, rigging, steering gear, auxiliary steering gear, windlass, general equipment, pumps, W.T. doors, ventilator coamings and covers, air- and sounding pipes (striking plates fitted), casings and boats.

Freeboard verified.

Examined internally and tested:

internally and tested:
Fore- and after peak tanks, oil fuel bunkers, main centre cargo tanks, side tanks and coffer-

dams .

When Anchors or Cables are supplied, the particulars are to be reported in the following form :—

ANCHORS.

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, BY STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd																
	3rd																
	Collective Weight																
	Stream.....																
	Kedge																

If Patent state name of Patentee.

*Indicate whether it is a 1st, 2nd, or 3rd bower.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

All spaces previously cleared, ceiling, lining and rust removed as required.

Steelwork afterwards coated and ceiling and lining replaced.

List of Endorsements:

List of Endorsements:

Indents in keel, bottom and side shell plating (port and starboard) dealt with as per the body of this report. Some minor indents still remain, but they do not, in our opinion, affect the efficiency or seaworthiness of the ship, and it is recommended the item remain in the List of Endorsement.