

No. 140412

PORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

Writing Report..... 19..... When handed in at Local Office. 20 AUG 1954 19..... Port of IVERPOOL 25 AUG 1954
Survey held at Fleetwood Date. First Survey 6/1/54 Last Survey 29/7 19 54
(No. of Visits 6)

on the Machinery of the ~~Wood, Iron or Steel~~ S.T. SPRINGWELL

Gross 286 Vessel built at Goole By whom Goole S.B. & R. Co. Ltd. When 1917 5
Net 113 Engines made at Glasgow By whom W. Beardmore & Co. Ltd. When 1917
Rule 80 Boilers, when made (Main) 1917 (Donkey) -
in Boilers 18 Owners Sun Steam Trawling Co. Ltd. Owners' Address
1323 (if not already recorded in Appendix to Register Book)
Donkey Boilers - Managers Port Fleetwood Voyage
Pressure - If Surveyed Afloat or in Dry Dock Both
Boilers 200 (State name of Dock) Wye Dock
Boilers -

Report No. Port
Details of Examination and Repairs (if any) Condition & Boiler Survey

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on Damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being entered in the body of the report, should be briefly summarised at the end of the report. State also the dates and any letters respecting this case

Cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined No damage reported

Damage report made by anyone else? If so, by whom?
Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes
Donkey none

For what reasons? What parts of the Boilers could not be thus thoroughly examined?

Means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? 23-7-54

Date of internal examination of each boiler 23-7-54 Present condition of funnel Efficient

Surveyor examine the Safety Valves of the Main Boilers? yes To what pressure were they afterwards adjusted under steam? 200 LBS

Surveyor examine the Safety Valves of the Donkey Boilers? yes To what pressure were they afterwards adjusted under steam? -

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes, and of the Donkey Boilers? -

Surveyor examine the drain plugs of the Main Boilers? none, and of the Donkey Boilers? -

Surveyor examine all the mountings of the Main Boilers? yes, and of the Donkey Boilers? -

Screw shaft now been drawn and examined? no Has it a continuous liner? - Is an approved oil retaining appliance fitted at the after end? -

Shaft now been changed? no If so, state reasons - Has the shaft now fitted been previously used? - Has it a continuous liner? -

Approved oil retaining appliance fitted at the after end? - State date of examination of Screw Shaft - State the wear down in the

Shaft Is electric light and/or power fitted? yes If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? no

Insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? no

Tests, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete

now placed on the shipway, propeller, after end of stern bush and outside fastenings of sea connections examined

Boiler examined through-out together with safety valves mountings, manholes doors and their fastenings

Boiler subsequently examined under steam when Safety Valves were adjusted to 200 lbs per sq inch.

Wear & tear) all plain tubes renewed

Observations, Opinion, and Recommendation:—

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.)

Machinery of this vessel so far as now seen is eligible in my opinion to be as now classed in the Register Book with fresh record of BS 7.54 now

per Section 23) BS £ 5: 00 Fees applied for, 19
Age or Repair Fee (if any) £ 3: 30 20 AUG 1954 Received by me,
(per Section 23.) £ 2: 00 19

Expenses (if chargeable) £ 2: 0: 0
Surveyor's Minute LIVERPOOL 24 AUG 1954

As now

BS 7.54

Signature of Surveyor
Engineer Surveyor to Lloyd's Register of Shipping.
Lloyd's Register Foundation

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to

now.

2.9
30/8/54



© 2021

Lloyd's Register
Foundation