

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

Port of KOBEDate of writing Report 8th July, 1953. When handed in at Local Office JUL 14 1953Date. First Survey 30th June, 1953, Last Survey 1st July, 1953. (No. of Visits 2)No in Reg. Book. Survey held at Tamano, Japan

S.S. "ASAKAZE MARU"

on the Machinery of the Steel

Tonnage { Gross 4995
Net 3502

MN As Per Rule -No. of Main Boilers 2HS " " " 5758No. of Donkey Boilers 1

Steam Pressure—

in Main Boilers 200in Donkey Boilers 200Vessel built at SunderlandEngines made at W. Hpl.

Boilers, when made (Main)

Owners Nakamura Steam Ship Co., Ltd.Managers Drydock

If Surveyed Afloat or in Dry Dock

(State name of Dock.) Mitsui, Tamano.By whom W. Gray & Co., Ltd.By whom Cen. Mar. E. Wks. Ltd.

(Donkey)

Owners' Address

(if not already recorded in Appendix to Register Book.)

Port Kobe

Voyage

When 1929 7

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

HULL

MACHINERY

BS x

10,51

ss Tri - 11,48

AS. 4,52.

MBS x 11,48BlrS 11,51msp 11,4815 CL 9,50

Fitted for oil fuel.

Last Report No. 02076Particulars of Examination and Repairs (if any) Propeller damage

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom? No

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time? No

If not, state for what reasons? -

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? -

State latest date of internal examination of each boiler? -

Did the Surveyor examine the Safety Valves of the Main Boilers? -

Did the Surveyor examine the Safety Valves of the Donkey Boilers? -

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? -

Did the Surveyor examine the drain plugs of the Main Boilers? -

Did the Surveyor examine all the mountings of the Main Boilers? -

Has the screw shaft now been drawn and examined? Yes Has it a continuous liner? Yes Is an approved oil retaining appliance fitted at the after end? No

Has shaft now been changed? No If so, state reasons? - Has the shaft now fitted been previously used? Yes Has it a continuous liner? Yes

Is an approved oil retaining appliance fitted at the after end? No State date of examination of Screw Shaft 30-6-53 State the wear down in the stern bush 4,2mm Is electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? No

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? -

Engine parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete

Now Done: Vessel placed in drydock, propeller, sea connection and their fastenings examined and found or now placed in good condition.

Repairs due to Damage: Damages stated to have been caused through touching the quay wall on the 22nd April, 1953 at Santiago Cuba, propeller examined throughout and found.

No.1 blade:- trailing edge bent over forward, now faired.

No.4 blade:- Blade tip at following edge bent over aftward for a length about 450mm, 40mm depth and broken 60mm length and 50mm depth, now faired and brazed.

Blade tip at leading edge bent over forward for a length about 600mm and crooked 70mm length.

Now faired and crack veed out and brazed.

Screw shaft drawn in, examined and found in good condition.

Interim Certificate No.C-15646 issued, copy attached hereto.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.)

The machinery of this vessel, so far as now seen, is in good condition and eligible in my opinion to remain as now classed with fresh record of screw shaft seen 7,53.

Survey Fee (per Section 23.) TS (CL) x¥ 6,000.

Special Damage or Repair Fee (if any) x¥ 10,000.

(per Section 23.) See Rpt. 8

Travelling expenses (if chargeable) -

Committee's Minute THURSDAY 13 AUG 1953

Assigned S. 7,53

Received by me, 19

Engineer Surveyor to Lloyd's Register of Shipping.

© 2021 Lloyd's Register Foundation

012003-012010-0093

Is a Certificate required? If so, to be sent to