

Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

25 OCT 1955

NAME "STANVAC VISAYAS 11"

REPORT

Man. No. 3977

Orders of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."— (Extract from Sub-Committee's Report, 24/5/52.)

PERIODICAL SPECIAL SURVEY (D) ~~was~~ partly held  
(Tanker 10 yrs old).

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in hundredths of an inch.

DECK	AMIDSHIP.					FORWARD.					AFT.					REMARKS.
	Original Thickness	Thickness by drilling.		Diminution if any.		Original Thickness	Thickness by drilling.		Diminution if any.		Original Thickness	Thickness by drilling.		Diminution if any.		
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.	
DECK																
Deck below																
Deck E	44	38	38	6	6	44	-	31	-	13	44	44	38	-	6	
Deck below D	44	R	38	-	6	44	S	S	-	-	44	44	44	-	-	
Deck (ge) C	44	R	R	-	-	44	38	38	6	6	44	38	44	6	-	R-Renewed
Deck B	44	R	R	-	-	44	38	44	6	-	44	38	44	6	-	S-Stealer
Deck A	44	R	R	-	-	44	44	38	-	6	44	44	44	-	-	
Deck PK	44	R	-	-	-	44	-	-	-	-	44	-	-	-	-	

Drillings at ends to be made in the vicinity of the peak bulkheads.

The class is subject to 30 fathoms of chain cable being supplied at the earliest opportunity, with Endorsement (B).

The MANILA Surveyor reports (3,55), the ship placed in dry dock, the principal part of the requirements of a SPECIAL SURVEY (D) complied with and extensive renewals and repairs effected to the deck and trunk plating also shell and ~~deck~~ plating.  
BULKHEAD

The thickness of the shell plating has been ascertained by drill testing with results as above which are considered satisfactory.

Two lengths of chain cable found worn to 1/32" beneath the renewal diameter and recommended to be renewed.

© 2021  
Lloyd's Register Foundation  
Cont/.....  
012047-012057-0114 1/2

"STANVAC VISAYAS 11"

IT IS SUBMITTED record of d ocking 3,55 be assigned, subject, to 30 fathoms of chain cable being supplied\* and 30 fathoms of chain cable (Cert.Nos. 53/PA.12997 and 53/PA.13001) being verified with test certificates at the earliest opportunity, the Notation of 'ss.Man. 3,55 (Dr)' being WITHHELD for completion of the Special Survey.

3,55 Man. Subject. \*30 fathoms renewed

IN S.R.L.  
(Bottom plating amidships set up 1").

ENDORSEMENT OF CLASS (B).

No.2 plate in sheerstrake (s.s.f.) indented.  
Shell plating (p.s.f.) in way of No.1 tank indented

} delete see  
26.20/2/57

S.S. PART HELD.

IT IS FURTHER SUBMITTED (before this case receives the consideration of the Committee) the Surveyors be informed it is concluded that -


- (1) there are 3 bower anchors on board the ship, *yes.*
- (2) the masts and rigging were examined from aloft, *yes.*
- (3) the Endorsement of Class (B) items have not been dealt with, *dealt with*
- (4) the shell drillings furnished for E.4 (s.s.), D.5 & 8 (p.s.) and E.5 (p.s.) are *not* indicative of the general condition of these plates but only of locally wasted spots, and be requested to furnish the particulars of the 30 fathoms of chain cable which were put on board in December of last year, and to state what arrangements have been made for the supply of 30 fathoms\* of chain cable, also the items remaining to complete the Special Survey, as it would appear from the reports the Special Survey is, in fact, complete. *supplied*

*LENGTH OF C.C.  
COMPLETED BY STEELER  
26/2/57* \* and renewal of 30 fms.

REFER ADMIN. (Estab) re qualifications and experience of Surveyor who has carried out this survey.

*RM.  
6.20.55*

*Mr. Innes consulted before writing closing letter  
Left.*



© 2021  
Lloyd's Register  
Foundation

2/2  
017047-02057-014