

32 Essential Independent Pumps (Identify by position)

33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls

34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?

35 Fresh Water Coolers 36 Lub. Oil Coolers 37 Heaters (state service)

38 Independent Air Compressors, Coolers & Safety Devices 40 Auxiliary

39 Air Receivers & Safety devices—Main

41 Oil Fuel Tanks (Not forming part of hull structure) 43 Have Evaporator Safety Valves been tested under steam?

42 Evaporators 45 Windlass 46 Fire Extinguishing Arrangements

44 Steering Machinery

AUXILIARY ENGINES (Identify by position)

ELECTRICAL EQUIPMENT

PROPULSION	PORT	STARBOARD	AUXILIARY EQUIPMENT
a Generators			l Generators & Governors
b Exciters			m Motors
c Air Coolers			n Switchboards & Fittings
d Motors			o Circuit Breakers
e Air Coolers			p Cables
f Control Gear, Cables, etc.			q Insulation Resistance
g Insulation Resistance			r Steering Gear Generators and Motors
h Insulating Oil Test			s Navigation Light Indicators
i Overspeed Governors			
j Magnetic Couplings			
k Air Gap			

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN	AUXILIARY, DONKEY or PRESS
Superheaters	
Safety Valves	
Mountings, Doors & Fastenings	
Safety Valves Adjusted to { Sat. Spt.	
Boiler Securing Arrangements	Exhaust Gas Heated Economisers
Main Economisers	Steam Generator Safety Valves Adjusted to
Steam Heated Steam Generators	Forced Circulating Pumps
Were Oil Burning System & Remote Controls examined working in accordance with Rules?	Funnel
Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?	

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main	Auxiliary (over 3 in. bore)
Were Copper Pipes annealed?	Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding them)

NOW DONE FOR SURVEY:-

It was reported by the Owners' Representative that, during the vessel's maiden voyage from Japan, brickwork in the starboard boiler front wall had fallen into the furnace floor. The ~~XXXX~~ STARBOARD boiler brickwork was examined at this time and the front wall bricks above fuel burner openings found loosened and the furnace floor partially sagged. Brickwork repairs were made at this port.

LEAVE THIS SPACE BLANK

Survey fees \$ 35.00

Damage fee ... Expenses... © 2020 3.25

Date when A/c rendered 21st September, 1929



Lloyd's Register Foundation

Total No. of Visits 44

92