

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

23 APR 1935

Date of writing Report 18-4-1935

When handed in at Local Office 18-4-1935

Port of

Aberdeen

No. in
Book.

Survey held at Aberdeen

Date, First Survey 13-4-35

Last Survey 14-4-1935

(No. of Visits 2)

9864 on the Machinery of the Wood, Iron or Steel

MV "JOLLY DAYS"

Gross 351
Net

Vessel built at Aberdeen

By whom J. Lewis & Sons Ltd.

When 1935.

Nominal
Horse Power

Engines made at Yencil.

By whom Patten, Ltd.

When 1935

of Main Boilers

Boilers, when made (Main)

(Donkey)

of Donkey Boilers

Owners F. W. Harlock.

Owners' Address

(if not already recorded in Appendix to Register Book.)

Port Harwich

Voyage

Coasting.

Main Boilers

If Surveyed Afloat or in Dry Dock

Dry

(State name of Dock.)

Particulars of Classification (which must be inserted
precisely as in Register Book & Supplements).

Last Report No. Port

Particulars of Examination and Repairs (if any) Installing Ind. Pump.

Periodical surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

is a damage report made by anyone else? If so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

his was not done, state for what reasons?

what parts of the Boilers could not be thus thoroughly examined?

what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

the latest date of internal examination of each boiler

the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

screw shaft now been drawn and examined?

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

shaft now been changed?

If so, state reasons

the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Completed.

During trials at sea the bilge pump crosshead, guide, and eccentric on extension of main engine shaft for driving bilge pump became overheated and somewhat scored. These parts have now been dressed up, re-assembled, tried under working conditions and found satisfactory.

A new crosshead is being supplied by the engine builders, to be fitted at the Owner's convenience. In my opinion this need not be noted against the vessel, as the crosshead now fitted, while somewhat scored, is efficient.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&M.S. 9,11, L.M.C. 9,11, or L.M.C. 140 lb., F.D., &c.)

CS 3,34,

See Aberdeen First Entry Report No. 18037.

y Fee (per Section 20)

£

:

:

Fees applied for

l Damage or Repair Fee (if any)

£

:

:

Received by me,

lling expenses (if chargeable)

£

:

:

19

Committee's Minute

Signed

FRI. 8 MAY 1935

See Abn. 18037

P. Fitzgerald

Engineer Surveyor to Lloyd's Register of Shipping.

© 2021

Lloyd's Register
Foundation

012229-012235-0125

Is a Certificate required? If so, to be sent to