

DISCLOSED  
SECTION  
Rpt. 9.

DISCLOSED  
SECTION  
No. 626

British Corporation

No. 59036

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

24 DEC 1954

Date of writing Report 22 Decr. 1954 When handed in at Local Office 22 Decr. 1954 Port of Cardiff  
No in Reg. Book. Survey held at Cardiff Date. First Survey 20 Decr. 1954 Last Survey 21 Decr. 1954  
(No. of Visits 2)

1/62/91 on the Machinery of the Wood, Iron or Steel new trawler 'Sata'

Tonnage { Gross 340 Vessel built at Stockton-on-Tees By whom Smiths Dock Ltd When 1931 Month 10  
Net 123 Engines made at Bedford By whom Smiths Dock Ltd When  
Nominal Horse Power 99 Boilers, when made (Main) 1931 (Donkey) -  
Owners Heath Street Ltd Owners' Address -  
No. of Main Boilers 1 Managers Heath Street Ltd Port Cardiff Voyage -  
No. of Donkey Boilers - If Surveyed Afloat or in Dry Dock afloat in dock  
Steam Pressure in Main Boilers 200 (State name of Dock.)

in Donkey Boilers - Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. 58869 Port Cardiff  
Particulars of Examination and Repairs (if any) Burn repairs.  
(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined no damage

Was a damage report made by anyone else? If so, by whom? no

Did the Surveyor personally go inside each Main Boiler separately and make a through examination at this time? yes

" " Donkey " " " "

If not, state for what reasons. What parts of the Boilers could not be thus thoroughly examined? -

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? -

State latest date of internal examination of each boiler 22.12.54 Present condition of funnel  satisfactory

Did the Surveyor examine the Safety Valves of the Main Boilers? no To what pressure were they afterwards adjusted under steam? -

Did the Surveyor examine the Safety Valves of the Donkey Boilers? - To what pressure were they afterwards adjusted under steam? -

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? no and of the Donkey Boilers? -

Did the Surveyor examine the drain plugs of the Main Boilers? - and of the Donkey Boilers? -

Did the Surveyor examine all the mountings of the Main Boilers? no and of the Donkey Boilers? -

Has the screw shaft now been drawn and examined? no Has it a continuous liner? - Is an approved oil retaining appliance fitted at the after end? -

Has shaft now been changed? - If so, state reasons. Has the shaft now fitted been previously used? - Has it a continuous liner? -

Is an approved oil retaining appliance fitted at the after end? - State date of examination of Screw Shaft. State the wear down in the stern bush. Is electric light and/or power fitted? yes If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? no

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? no

Engine parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Survey complete.

At the request of Owners Superintendent examined port side of port furnace, which had been extensively welded up along line of fire bars.

Repairs effected: welded port side of port furnace cut out and a new panel welded in. Hydraulic and steam test on boiler passed satisfactorily.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9.11, B&MS 9.11, LMC 9.11 or LMC 140 lb., FD, &c.)

OS 3.34

The machinery of this vessel is efficient in my opinion & remains as now classed without fresh record

Survey Fee (per Section 23) £ 5.50 Fees applied for 22 Decr. 1954

Special Damage or Repair Fee (if any) (per Section 23.) £ 5.50 Received by me, 19

Travelling expenses (if chargeable) £ -

Committee's Minute TUESDAY 18 JAN 1955

Assigned As reported

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

012346-012357-0195



Berlin repair

It is submitted that this  
vessel is eligible to remain  
as **CLASSED**.

W

2.7.55

12 JAN 1955



© 2021

Lloyd's Register  
Foundation