

PORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

No. 6171.

of writing Report 14th SEPT. 1946. When handed in at Local Office.....

Survey held at RUSHBROOK.

on the Machinery of the Wood, Iron or Steel S.S. "IRISH ELM".

Gross 4199
Net 2541
inal 350
Power Main Boilers 288.
Donkey Boilers ✓
Pressure —
Main Boilers 18048.
Donkey Boilers ✓

Vessel built at SUNDERLAND
Engines made at 06.
Boilers, when made (Main) 1910
Owners IRISH SHIPPING CO.
Managers

By whom J. L. THOMPSON & SONS LTD
By whom J. DICKINSON & SONS LTD. When 06.
(Donkey)

Owners' Address

Port DUBLIN Voyage

Surveyed Afloat or in Dry Dock RUSHBROOK.
(State name of Dock.)

Report No. Port

culars of Examination and Repairs (if any) +L.M.C. T.S.

al Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly mentioned at the end of the report. State also the dates and initials of any letters respecting this case.

age cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

damage report made by anyone else? If so, by whom? ✓

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes

" Donkey " " "

state for what reasons ✓

What parts of the Boilers could not be thus thoroughly examined? ✓

special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

atest date of internal examination of each boiler 27th July 1946.

Present condition of funnel

good

Surveyor examine the Safety Valves of the Main Boilers? yes

To what pressure were they afterwards adjusted under steam? 180 lb.

Surveyor examine the Safety Valves of the Donkey Boilers? ✓

To what pressure were they afterwards adjusted under steam? ✓

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes

, and of the Donkey Boilers? ✓

Surveyor examine the drain plugs of the Main Boilers? ✓

, and of the Donkey Boilers? ✓

Surveyor examine all the mountings of the Main Boilers? yes

, and of the Donkey Boilers? ✓

screw shaft now been drawn and examined? yes

Has it a continuous liner? yes

Is an approved oil retaining appliance fitted at the after end? ✓

ft now been changed? No. If so, state reasons ✓

Has the shaft now fitted been previously used? ✓

Has it a continuous liner? ✓

pproved oil retaining appliance fitted at the after end? ✓

State date of examination of Screw Shaft 7th August 1946

bush 32" Is electric light and/or power fitted? yes If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? yes

insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? yes

Survey is not complete, state what arrangements have been made for its completion and what remains to be done complete

done: - Vessel placed in dry dock. Propeller, screw shaft, stem bush, connections and fastenings examined. Cylinders, pistons, slide valves, crank, thrust and intermediate shafts, coups, condenser (tested). The valves, cocks, pipes and strainers of the piping arrangements examined. Valves examined internally and externally with mountings, safety valves, hole doors and fastenings. Safety valves were adjusted under steam to the pressure stated. Cam tapes annealed and tested examined under hydraulic pressure 360 lb. per sq. in. and afterwards examined internally as far as practicable. Electric installations examined and tested under working conditions (continued)

ral Observations, Opinion, and Recommendation: The machinery of this vessel so far

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11, LMC 9,11 or LMC 140 lb., FD, &c.)

as 3,34,

now seen is in good condition and eligible in my opinion remain as now classified with fresh record +L.M.C. 9.46 and rating TS as seen 8.46.

Fee (per Section 29) +L.M.C. £17 : 0 : 0

Fees applied for
16 SEPT. 1946

Damage or Repair Fee (if any) £ 3 : 0 : 0

Received by me,

ding expenses (if chargeable) £ : : 19

FRI. 18 OCT 1946

R. B. Green.

Engineer Surveyor to Lloyd's Register of Shipping.

tee's Minute

ned


1.8.46

Three 9.46
CERTIFICATE WRITTEN

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? It so, to be sent to

012606-012609-003742



© 2021
Lloyd's Register
Foundation

Repairs wear & tear.

H.P. piston rod skinned neck and gland bushes, renewed.

H.P. piston rings renewed.

I.P. and L.P. piston rods renewed. Certificate No. 43281 attached.
neck and gland bushes renewed.

I.P. piston rings renewed.

L.P. crosshead pins remitted.

H.P. I.P. L.P. valve spindles skinned, neck and gland bushes
renewed. all valve gear overhauled adjusted and placed in
good condition.

Condenser a number of tubes renewed.

Inboard bilge pump neck & gland bushes renewed.

Circulating pump bucket-ring renewed.

Auxiliary condenser new fitted.

Ballast pump. a new Lamont No 20160, 10" x 10" x 10" fitted.

General service pump. buckets, piston rings, and valve spindles
renewed. New auxiliary feed pump, bucket-rings renewed.

Bilge pipe lines overhauled throughout vessel, pipes and bands
renewed where required. No 4 hold bilge suction C.I. band renewed.

Tank suction pipe No 2, No 4 hold bilge suction C.I. band, main bilge line
stainless band. C.I. renewed. a number of lead pipes repaired.

Boilers.

Port. all plain tubes renewed.

Port Combustion Chamber radius of back plate flange built
up by electric welding. one screw stay removed plate
built-up and stay renewed.

Starboard bottom door built-up by electric welding.

Starboard. Port Combustion Chamber. 2 stay nuts renewed.

Centre d. d. 3 screw stays renewed, plate in
way built up and stays renewed.

Port bottom man hole flange built-up by E.W. new dogs
supplied for door.

Starboard bottom man hole door dogs renewed.

Minor repairs to mountings.

Tunnel crawl renewed.

Electric installations all dismantled overhauled placed in good
condition with part new material megger tested and examined
under working conditions.

Spares replaced to Rules.

The machinery tested under working conditions.

R. B. Green.



© 2021

Lloyd's Register
Foundation

0037 2/2