

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 41025

Date of writing Report

May 5 41

When handed in at Local Office

May 5 41

(Received at London Office)

-2 JUL 1941

No. in
Reg. Book

Survey held at

Hoboken N.J.

Date, First Survey

22nd MarchLast Survey 29th April 1941

(No. of Visits 2)

Tonnage

Gross 4115
Net 2535

Vessel built at Sunderland.

By whom J. L. Thompson & Sons Ltd.

Year. Month.

Nominal
Horse Power

350

Engines made at Shields

By whom J. L. Thompson & Sons Ltd.

When 1910-1

No. of Main Boilers

2

Boilers, when made (Main) 1910

By whom J. L. Thompson & Sons Ltd.

When 1910

No. of Donkey Boilers

1

Owners Compagnie Generale de Navigation

Owners' Address

Steam Pressure—
in Main Boilers

180

Managers Irish Shipping Co.

(if not already recorded in Appendix to Register Book.)

in Donkey Boilers

✓

If Surveyed Afloat or in Dry Dock

H. T. Tait & Lang & Co.

Port

Dublin Voyage

Last Report No.

Port

Particulars of Examination and Repairs (if any) L.M.C. - CL

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and dates and initials of any letters respecting this case.

1 damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey " " "

this was not done, state for what reasons?

and what parts of the Boilers could not be thus thoroughly examined?

So what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boiler?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

Is screw shaft now been drawn and examined?

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Is shaft now been changed? If so, state reasons

Is the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Is electric light and/or power fitted?

the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

W.D.M. The vessel placed in dry dock, propeller, stern bush & its fastenings, sea cocks & valves & their fastenings examined, now good. The Tail Shaft drawn for examination & found good, Stern bushing rewooded & shaft refitted in good order.

Main engine HP & LP cylinders pistons rods, valves & chests, crossheads, valve gear, crank shaft, thrust shaft & intermediate shafting & their bearings examined & found in good order. Condenser examined & tested, made & proven tight.

The circulating, air, feed, & ballast pumps, attached pumps & the pumping arrangement examined & tested under working conditions & found or now placed in good order. The electric installation tested to rule requirements, now good.

The Main boiler examined internally & externally together with their valves & P.T.O.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, D.&M.S. 9, 11, & L.M.C. 9, 11, or CS 3, 34.)

Vessel is eligible in my opinion to remain as classed with full record of + L.M.C. 4.41 and of Tail Shaft Secu (CL) 3.41.

Fee (per Section 29) L.M.C. \$110.00

BS 30.00

CL 20.00

ELECT 25.00

Fees applied for

2-5-1941

Received by me

5-5-1941

Damage or Repair Fee (if any)

(per Section 29.)

Selling expenses (if chargeable)

Committee's Minute

signed + L.M.C. - 4.41.

T.S. 3.41.

NEW YORK MAY 7 - 1941

Engineer Surveyor to Lloyd's Register of Shipping.

S/S "LEDA"

& mountings, now good. The steam pipes subjected to hydraulic test as per rule & found good.

The Boilers examined under steam & their safety Valves adjusted as noted above.

Minor repairs effected.

JMS

