

No. 117314

(Received at London Office _____ NOV 1948 _____)

Date of writing Report 11 NOV 1948 19..... When handed in at Local Office 11 NOV 1948 19.....

Port of LONDON

No. in *Survey held at* LONDON *Date.* *First Survey* 21-7-40 *Last Survey* 30-7-40
Eg. Book. *(No. of Visits)* 4

80049 on the Machinery of the ~~Wood, Iron or Steel~~

SS "WILLOWBANK"

Year. Month.

Tonnage { Gross 7289		Vessel built at	Portland, Me.	By whom	New England S.B. Corp.	When	1944
Net 65207		Engines made at	Springfield, Mass.	By whom	Springfield Mach. & Fdry. Co.	When	1944
Nominal Horse Power 688 MN		Boilers, when made (Main)	1944	(Donkey)	--		
No. of Main Boilers 2		Owners	Bank Line Ltd.	Owners' Address			
No. of Donkey Boilers --		(If not already recorded in Appendix to Register Book.)					
Steam Pressure --		Managers	Andrew Weir Shipping & Trading Co. Ltd.	Port	Glasgow.	Voyage	
in Main Boilers 250/230		Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).					
in Donkey Boilers --							

Last Report No. _____ *Port*

Particulars of Examination and Repairs (if any) Blowing & Boilers repairs

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.....

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined. Not required

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? 20

32 " Donkey "

If not, state for what reasons Summary of Refrain only What parts of the Boilers could not be thus thoroughly examined? ☒

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler.

Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boilers? No To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers?..... To what pressure were they afterwards adjusted under steam?.....

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? no, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? ☒ Yes, and of the Donkey Boilers? ☒ Yes

Did the Surveyor examine all the mountings of the Main Boilers? No, and of the Donkey Boilers? Yes

Has the screw shaft now been drawn and examined? ☒ Has it a continuous liner? ☒ Is an approved oil retaining appliance fitted at the after end? ☒

Has shaft now been changed? _____ If so, state reasons _____ Has the shaft now fitted been previously used? _____ Has it a continuo

Is an approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft State the wear down in the

stern bush ✓ Is electric light and/or power fitted? yes If so, did the Surveyor examine the generators, motors, switchgear, cables and

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

how done for advancement of classification survey
Main engines :- HP top and bottom end pins and bearings, hot main bearing and journals examined
Main condenser examined and tested.
Auxiliaries :- Outboard oil fuel pump, oil fuel transfer pump and sanitary pump, opened up and examined in entirety.
Refrigerators :-
Hot Boilers :- All tubes in fire now renewed at this time (Wear & tear)

General Observations, Opinion, and Recommendation:— The machinery of this vessel as now run
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11 or LMC 9,11 or LMC 140 lb., FD, &c.)
is in a good and efficient condition and eligible in our opinion to have the
the record of LMC with date, when the survey is completed.


To Collect

Survey Fee (per Section 29)	<i>Enrollment 3/11</i>	£ 18	:	:	-	Fees applied for
Special Damage or Repair Fee (if any) (per Section 29.)		£ 3	:	3	0	<i>11 NOV 1948</i>
Travelling expenses (if chargeable)		£	:	:		Received by me, 19

Committee's Minute

Assigned _____ LMC MS 6.47

W. Mason for E. M. Lelley, D. G. Rankin & Self
Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register
Foundation

012624-012630-0073