

Rpt. 8

Port YOKOHAMA

No. 2635

Date of writing Report 23rd June, 1958

When handed in at Local Office JUN 24. 1958

Received London

JUL 1958

Survey held at Yokohama

No. of Visits One

First Date and 19

Last Date 22nd June 1958

REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B. 13560 on the Iron or Steel M.S. "HIKAWA MARU" Tons gross 8092
 Built at Kawasaki Dockyard Co., Ltd. By Whom
 Owners Kawasaki Kisen K.K. & Nippon Kaiun K.K. Owners' address (If not already in R.B.) Kobe
 Managers Port of Registry
 Surveyed Afloat or in Drydock Afloat Name of Dock Asano Dock Date of last examn. in Drydock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.
 Last Report: No. 1136 Port Kobe
 To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS		Machinery	
Date of Special and of Drydocking Surveys, etc.			
+	100 A1	+	LMC
	Carrying oil fuel F.P. above 150° F.	Eng. N	7/55
	or veg. oil in MT	nd	7/55
	Dkg. 4/57	d	4/57
		CL	7/55

Give dates and references to any letters relating to this Report

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined. Freeboard as marked on ship and now verified ft ins
 Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR REPAIRS

NOW DONE:—

The heating coils in P. & S. Deep Tanks in way of No.3 Hold, replaced at this time and tested by hydraulic pressure to 14 kg/cm² on completion.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? No
 Is Classification Certificate required? If so, to be sent to No
 If so, is the Report sent now, or when will it be sent? —
 Has Interim Certificate been issued? Yes

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:— "to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

This vessel is eligible in my opinion to be continued as classed without fresh record of docking subject to all conditions at present attached to the vessel's class being dealt with as previously recommended.

Surveyor to Lloyd's Register of Shipping

THURSDAY 31 JUL 1958

Date of Committee

Minute

DS 6,58 subject

DBS 6,58 TS 6,58

Note & minute Kob. (H) (H)

TUESDAY 26 AUG 1958

Annau without pl. con (h)

Noted for Header

Lloyd's Register Foundation

013201-013210-0114

TABLE 1

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR SURVEY

Items	Now Examined	Tanks	Now Examined Internally	Now Tested
	YES NO or NONE			
Shell plating, sternframe and rudder cleaned, examined and recoated in drydock		F.P. Tank		
Rudder lifted		A.P. "		
Weather Decks, Superstructures and Casings		D.B. Tanks (indicate Oil Fuel and Cofferdams)		
Hatchways, Covers, closing and securing appliances				
Ventilator coamings, skylights, companionways and closing appliances		Fresh Water Tanks		
Holds		Deep Tanks		
'Tween Decks		Oil Fuel Bunkers and Settling Tanks		
Fore Peak Spaces		Side Tanks		
After " "		Wing Tanks		
Engine Space		Other Tanks		
Boiler "		Cargo Tanks (Tankers)		
Under Engines and Boilers				
Tunnel and Well		Cofferdams		
Coal Bunkers		Pump Rooms		
Chain Locker				
Other Spaces				
		Have Tanks now Examined been Cleaned as Necessary?		
		Have Strums in Cargo Tanks (of Tankers) been removed?		
		Have Tanks been Retested as necessary after completion of any Repairs?		

Have the spaces now surveyed been cleared and cleaned as necessary?

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules?

Have the bilges been cleaned out and examined? Has cement in bottom been examined?

Has steelwork had rust removed and afterwards been recoated as necessary?

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork?

Has a Load Line Survey been held? If so, state which

Have the shell and deck plating been drilled as per Rule? If so, Report 8(Dr) to be attached

Have any alterations to the approved scantlings and arrangements now been effected? If so, report details in body of Report.

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

TABLE 2

The present condition of the following parts in so far as examined is to be reported:—

Shell plating	Ceiling and Cargo Battens	Sluice Valves examined and found
" " in way of side scuttles	Cement or Asphalt	Air and Sounding Pipes
Rudder and Sternframe	Cargo and other Hatchways	Doubling Plates under Sounding Pipes
Decks	Hatches and closing appliances	Masts and Rigging examined and found
Superstructures and their closing appliances	Ventilators, their coamings and closing appliances	Condition, how ascertained (State if wedges removed)
Coamings and Casings	Companionways and Skylights	Chain Locker
Beams and Fastenings	Shell Openings	EQUIPMENT
Frames	Ash Shoots	Equipment Letter
Reverse Frames	Overboard Discharges and Scuppers	Anchors, No. of Condition
Longitudinals	Freeing ports	Cables (State if now ranged and examined)
Transverses	Steering Gear (Main and Auxiliary)	" length mean diam.
Floors	examined and found	" Rule Length Size
Keelsons	Windlass examined and found	Hawsers and Warps
Stringers	Pumps " " "	State if any Anchors or Chain Cable have
Inner Bottom Plating	W.T. Doors " " "	now been supplied or retested, if so,
Bulkheads and Tunnel		complete Report 8(Eq) and attach.

Have conditions (A) or endorsements (B) of Class (if any) been dealt with? See Below


REMARKS, REPAIRS, Etc. (Contd.)

Survey Fee ¥ 10,000.-
 Special attendance ¥ 8,000.-
 Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable)..... ¥ 500.-

Second Surveyor's Fee (if any)

Date when A/c. Rendered



© 2021

Lloyd's Register
 Foundation
 JUN 24 1958