

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office)

JAN 11 1938

Date of writing Report 8-1-1938 When handed in at Local Office 8-1-1938 Port of Leith

No. in Reg. Book. Survey held at Burntisland Date, First Survey 3-12-37 Last Survey 27-12-1937 (No. of Visits 4)

on the Machinery of the ~~Wood, Iron or Steel~~ S.S. "BRASTEII."

Tonnage Gross 1075.56 Net 605.4 Vessel built at Burntisland By whom Burntisland S.B. Co. Ltd. When 1937

Engines made at By whom North Eastern Marine (Donkey) When

Boilers, when made (Main) Owners The Hudson Steamship Co. Ltd. Owners' Address (if not already recorded in Appendix to Register Book.)

No. of Main Boilers Managers Port London Voyage

No. of Donkey Boilers Steam Pressure in Main Boilers # Surveyed Afloat or in Dry Dock In Stocks

in Donkey Boilers (State name of Dock.)

Last Report No. Port

## Particulars of Examination and Repairs (if any) Fitting out.

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

If this was not done, state for what reasons?

And, what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Has screw shaft now been drawn and examined? Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

The sea-cocks and valves have been efficiently fitted in place and the stern frame has been bored out, the stern tube & propeller shaft fitted. Propeller shaft marked LLOYD'S N° 554, J.E.S. 24-11-37.

The bilge suction pipes to the hold are carried through the cross-bunker, protected by wood ceiling.

The vessel has been towed to Walloway to have the engine & boiler fitted on board, and the Survey will be completed at that port. Surveyors advised.

The dates of Survey are as follows:-

Stern frame bored out 3-12-37

Stern tube fitted 9-12-37

Sea connections & screw shaft fitted 15-12-37.

General Observations, Opinion, and Recommendation:—The above information is forwarded for

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.&M.S. 9, 11, & L.M.C. 9, 11, or

LMC 140 lb., F.D., &c.)

CS 3, 34,

the consideration of the Committee.

Survey Fee (per Section 29) £ : : Fees applied for 19  
Special Damage or Repair Fee (if any) £ : : Received by me, 19  
(per Section 29.)  
Travelling expenses (if chargeable) £ : :

Committee's Minute

FRI 4 FEB 1938

Assigned S. N. W. 95876

Engineer Surveyor to Lloyd's Register of Shipping.

013260-013267-0136

Lloyd's Register Foundation