

Im, 12, 15.

\* *Manoala*

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel S.S. "EUDUNDA"*

Rpt. *Syd*  
*Hub*

No. *1307*  
*3280*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *7353*

Depth "d" -

Framing: Table No. -

Description *Longitudinal framing*

Longitudinal No. *22437*

*Shelter*

Proportions Length = *9.8*  
Depth =

Deck Sheerstrake and other scantlings as approved for vessels built in the Longitudinal System

Survey Completed at Melbourne and damage to Shell & Longitudinal etc, caused through striking another vessel when lying alongside, repaired. The Daverton pump has been dispensed with for the present.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *100-A-1. (Steel) "Shelter Deck"* with freeboard, "as recommended. The Summer freeboard of *2' 7 1/2"* from centre of disc to top of statutory deck line at *Upper* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

*1 Deck (Steel) & Shelter (Dk) Steel & Webframes, Longitudinal framing*

*Cell DB 276' 882t, FPT 118t, APT 204t*

*FK, Collision BH to Shelter Dk, ABH to Upper Dk, Cam, A.C.P.*

*Date of build 9.80*  
*16.11.71*

*It is concluded a hand pump is fitted to the space above the fore peak tank or other efficient means for drainage provided but the Surveyors should be requested to state if this is so*

BEAMS, Bridge Deck, Angle, Bulb Angle, Plate, {

Tee Bulb or Channel .....

Angles on upper edge


..

Tie Plates .....

Deck Material and thickness

013346-013355-0293

uld



*Said to be 7.12.71*

*17.10.24*

© 2021

Lloyd's Register Foundation