

as fitted... 39.3 c.m.² Pressure to which they are adjusted 140 lbs. Are they fitted with ease

In case of donkey boilers, state whether steam from main boilers can enter the donkey boiler

4E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

HIP'S NAME "YESILIRMAK"

REPORT Rot No. 38589

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Structure of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

The machinery of this non-propelled floating sheerlegs appears to have been built in accordance with the Rules and the approved plans, and IT IS SUBMITTED she is eligible to be classed *DB 9,54

DB 140 lb.

It is concluded that the approved pumping arrangements have been fitted aboard the vessel but this should be confirmed by the Rotterdam Surveyors.



13.12.54.

013783 - 013793 - 0140

Centre 200 x 18 7/8

Length as per Rule (638 7/8) 600

Distance apart 210 7/8

each welded girders

Working pressure per Rules

under
ted.
streng
L. de
er
7/8
7/8
ed.
of stay
front...
back...
h and t
No. c