

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 18 MAY 1927 When handed in at Local Office 21 MAY 1927 (Received at London Office)

No. in Reg. Book. 60840 Survey held at Fleetwood Date, First Survey 25/2/27 Last Survey 13/5/1927 (No. of Visits 8)

Tonnage { Gross 324 Net 149 Vessel built at Selby

Nominal Horse Power { 87 N.H.P. Engines made at Hull

No. of Main Boilers One Boilers, when made (Main) 1918 By whom Cochran & Sons When 1918-9

No. of Donkey Boilers ✓ Owners Sam Robford & Co. Ltd. (Donkey) ✓ By whom C D Holmes & Co. Ltd When 1918

Steam Pressure in Main Boilers ✓ Owners' Address 17 Throgmorton Street, E.C.2. (if not already recorded in Appendix to Register Book).

in Donkey Boilers ✓ Port Fleetwood Voyage

If Surveyed Afloat or in Dry Dock Wyr Dock & Slip (State name of Dock.)

Last Report No. Port

Particulars of Examination and Repairs (if any) Reinstatement of

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " "

If this was not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

What is the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft? 1/8"

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done? Complete.

All cylinders, pistons, valves & chests, crank & thrust shafting, condenser, auxiliaries, pumps with valves & connections examined & found in good condition. Main steam pipe annealed & tested to 400 lbs./sq. in.

Vessel placed on slipway; the propeller, stern bush, sea connections & their fastenings examined. Screw shaft drawn examined & found in good condition.

The Boiler examined internally & externally with mountings found in good condition. Afterwards examined under steam & safety valves adjusted to 200 lbs./sq. in.

Main stop valve seat renewed. Machinery overhauled & adjusted and afterwards manoeuvred under working conditions.

General Observations, Opinion, and Recommendation:—The Machinery of this Vessel is in good condition and in our opinion eligible for re-instatement of class, and to have record of LMC 5.27 & screw shaft seen CL 5.27.

Fee (per Section 25) £ 8: -

Damage or Repair Fee (if any) £ 1: -

Other Expenses (if chargeable) £ 1: 14: 0

Committee's Minute

Signed

CERTIFICATE WRITTEN 8.2.27

Fees applied for

Received by me, 22.7.1927

Received by me, 22.7.1927

Received by me, 22.7.1927

Received by me, 22.7.1927

Received by me, 22.7.1927

Received by me, 22.7.1927

Received by me, 22.7.1927

CW Reed & J. Campbell 2021

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

013890 - 013899 - 0335

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to

Reclassification.
Engines & Boilers examined
throughout.

It is submitted that
this vessel is eligible for
THE RECORD. HMC 5.27

55.27 C.L.

(5) 200th.

24/5/27

24.5.27

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation