



FOUND

Windlass starboard gypsy block coupling cracked in way of one engaging dog.

Starboard chain cable securing attachment bottle screws sheared.

Welded butt to main deck port alley (mid ship) cracked where welded in way of frame No.63.

Ship side frames No.80,81, starboard side in way of stock hold cracked through welding.

Main condenser overboard discharge pipe cracked and temporarily repaired (partly corroded).

All removals necessary in order to carry out the above recommendations to be afterwards replaced in good conditions.

It is also recommended that all new and disturbed work be coated and spaces cleaned out on completion of repairs.

The above recommended repairs are to be carried out in a satisfactory manner so as to place the vessel in the same condition as before the alleged casualty was sustained.

RECOMMENDED

Windlass gypsy block to renew or repair.

Starboard chain cable securing attachment bottle screws to renew.

Butt strap welding to main deck to vee cut and re-weld.

Starboard side frames 80, 81, defective welding to vee cut and reweld.

16" steel overboard discharge pipe to renew 0ft.

M. DAWOOD



© 2021

Lloyd's Register Foundation