

No. 6746

port of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

TUE. 1 MAR. 1921

of writing report	6	1	10 21	When handed in at Local Office	6..1.	10 21	Port of Sydney	
in book.	Survey held at Sydney, N.S.W.				Date, First Survey	27.10.20	Last Survey	24.12.1920
					Ex		(No. of Visits)	14.
<u>45 in the Machinery of the Wood, Iron or Steel T.S.S. "MARELLA" WANEHE Master Mariner</u>								
Gross	7071	Nt	3991	Vessel built at Hamburg. By whom Reihardt's Schuppen When 1914.				
Entered	716	Power	3	Engines made at Hamburg. By whom "	When 1914.			
Main Boilers	3	Boilers, when made (Main)	1914	(Donkey)				
Donkey Boilers	1	Owners	Burns Philips & Co. Ltd. Port London Voyage Singapore.	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).				
Pressure in Joliers	127	If Surveyed Afloat or in Dry Dock	Woolwich Dry.	CHARACTER.				
only Boilers		(State name of Dock.)	Circular Lucy.	Date of last Survey and of Periodical Surveys.	Years	Assigned	Machinery and Boiler Survey (including date of N.B., if any).	

Report to Port

Particulars of Examination and Repairs (if any) Examined by Surveyor L.R.

Particular Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of damage, the cause of which must be stated, should be separated from Repairs due to other causes; and being detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Was a damage report made by anyone else? If so, by whom?

Original classed in Germanischer Lloyd.

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Yes

Donkey " "

"

was not done, state for what reasons?

at parts of the Boilers could not be thus thoroughly examined?

at special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Surveyor examine the Safety Valves of the Main Boiler?

Yes

To what pressure were they afterwards adjusted under steam? 227 lbs.

Surveyor examine the Safety Valves of Donkey Boiler?

Yes

To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Yes

and of the Donkey Boiler?

Surveyor examine the drain plugs of the Main Boilers?

Nil

and of the Donkey Boiler?

Surveyor examine all the mountings of the Main Boilers?

Yes

and of the Donkey Boiler?

new shaft now been drawn and examined?

Yes

Is it fitted with continuous liner?

Yes

or two liners?

or is it without liners?

shaft now been changed?

No If so, state reasons

shaft now fitted new?

Has it a continuous liner?

or two liners?

or is it without liners?

distance between lignum vite of stern bush and top of after bearing of screw shaft?

Starboard $\frac{1}{8}$ ", Port $\frac{1}{8}$ " bare.

Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Completed

Complie Special Survey now held. Section 48 of the Rules has been complied with.

This vessel placed in dry dock both Propeller shafts drawn examined and found good. Propellers good Sea cocks and valves examined good. Discharges good. Cylinders Pistons Valves Pumps Condensers Pipes and Roscs examined and all found good Crank Shafts Thrusts and Tunnel Shaving exposed and found in good condition. Arrangement of Valves and piping examined and found in order except the fact that no independent Donkey Bilge Suctions were fitted; Two $3\frac{1}{2}$ " direct Bilge Suctions now fitted one on Port and one on Starboard side each to

General Observations, Opinion, and Recommendation:— The Engines & Boilers P.T.O.

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.M.S. 9,11, or L.M.C. 9,11, 140 lb., F.D., &c.)

of this vessel, which was classed in another Register has now been Surveyed by the Surveyors to Lloyds Register; with a view to classification in Lloyds Register

Fee (per Section 28).....

All Damage or Repair Fee (if any) (per Section 28).....

Billing Expenses (if chargeable).....

Committee's Minute FRI. 4 MAR. 1921

Signed

Lloyd's 12.20

Fees applied for	8.1	1921
Received by me,		
	19	

A. C. Heron.

Engineer Surveyor to Lloyd's Register of Shipping.

FRI. 10 FEB. 1922

FRI. MAY. 191922

TUE. 28 FEB. 1922

R 015009-015019-015029

A Certificate required to be sent to

Insert Character of Ship and Machinery precisely as in the Register Book.

A Certificate required to be sent to

Lloyd's Register Foundation

I have submitted the
notations recommended on
the hull for acceptance.
Sept 12. 20.