

machinery of the s.s. "John", of R&A, No. 26885 in the Register Book.

The piston rings and the caplan box for H.P. piston renewed.

The I.P. liner, piston and piston rings renewed. Rod dressed up in laths.

The alignment of the crank shaft re-adjusted and the main bearings lower halves re-metallized.

All pumps overhauled and repaired as necessary.

The balance wheel for the lighting set repaired by a steel ring shrinked on the nave (cracked).

Part of the back plate of port combustion chamber of the port main boiler renewed. Screw stays in way renewed.

25 ordinary tubes in the starboard main boiler renewed.

The electrical installation overhauled.

Alterations:

A 170 M² superheater has been fitted, manufactured by A-B. Götawerken in accordance with plans approved at Gothenburg 21.2.1945. The superheater has been tested after erection in place to 50 kgs. per square cm. and found in order.

Sten Jansson

HS 5834 #

MN 409

Sgt