

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

Date of writing Report 10 July 1952 When handed in at Local Office 10 July 1952 Port of Antwerp
 No in Reg. Book. Survey held at Ghent Date. First Survey 25 June Last Survey 25 June 1952
 (No. of Visits 1)

26007 on the Machinery of the Wood Iron Steel Tw. Se. M/V "DRAKELOW" (ex. Christina Dawn 52)
90404

Gross 313 Vessel built at assembled by General By whom ✓
 Tonnage Net 163 Engines made at Colchester By whom Davey Paxman & Co. When 1945
 Nominal Horse Power 145/152 Boilers, when made (Main) ✓ (Donkey) ✓ When 1945
 Owners Drakelow P.S. Co. Owners' Address ✓ (if not already recorded in Appendix to Register Book.)

No. of Main Boilers ✓ Managers ✓ Port London Voyage ✓
 No. of Donkey Boilers ✓ If Surveyed Afloat or in Dry Dock Ghent Berth N° 53
 Steam Pressure in Main Boilers ✓ (State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. Years assigned now expired. Machinery and Boiler Surveys (including date of N.B., if any)

AI with forward 7.51 LMC 8.51
 Classes 18.51 ES 8.50
 SS Ship - 8.51

For service U.K., Eire, excluding West Coast, Channel Islands & Continent between River Elbe & Brest.

in damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined yes, but not required

Was a damage report made by anyone else? If so, by whom? Salvage Surveyor

Did the Surveyor personally go inside each Main Boiler separately and make a through examination at this time? ✓

Did the Surveyor personally go inside each Donkey Boiler separately and make a through examination at this time? ✓

If not, state for what reasons What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? SEE SPL. NOTE S.R.L. (MACHY.)

State latest date of internal examination of each boiler Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boilers? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of the Donkey Boilers? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓ and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓ and of the Donkey Boilers? ✓

Has the screw shaft now been drawn and examined? ✓ Has it a continuous liner? ✓ Is an approved oil retaining appliance fitted at the after end? ✓

Has shaft now been changed? ✓ If so, state reason ✓ Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓

Is an approved oil retaining appliance fitted at the after end? ✓ State date of examination of Screw Shaft ✓ State the wear down in the stern bush ✓

Is electric light and/or power fitted? ✓ If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

Engine parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

Now done: Attention board as requested by the Master and witnessed satisfactory running trials of Port Main Engine and manoubring of the same tested.

It was stated by the Chief Engineer that on the 15th June 1952, on voyage to Ghent, Port M.E. was using excessive oil, and the A3 + A4 cylinders were running hot. P.M.E. has been stopped for investigation, leak could not be detected. P.M.E. has been started again, with the same results oil consumption was still high. P.M.E. was stopped and vessel proceeded to Ghent on 18th M.E. only.

It was stated that upon examination of P.M.E. by the ship's staff at Ghent the cambox was leaking and the pushrods rubber tubes loose and deteriorated.

Repairs were carried out by the ship's staff with satisfactory results.

It is stated by the Master that all pushrod rubber tubes will be renewed at vessel's arrival at London, direct from Ghent.

General Observations, Opinion, and Recommendation.—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9.11, B&MS 9.11, LMC 9.11 or LMC 140 lb., ED, &c.)

Report forwarded for the information of the Committee.

Survey Fee (per Section 29) £ 1400. Fees applied for 11-7-1952

Special Damage or Repair Fee (if any) (per Section 29.) £ 37. Received by me, 19.

Travelling expenses (if chargeable) ✓

Committee's Minute TUES. 12 AUG 1952

Assigned Deferred - awaiting Off Rpt