

The class is subject to stbd. main engine crankpins & journals of N° 1 & 2 units being again examined before the end of 12.56 and that N° 1 diesel generator be examined under working conditions after the blower **5 E**
has been fitted.

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

4 FEB 1957

P'S NAME CAPE TOWN CASTLE

REPORT 500

No. 23975

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/8/92.)

of Survey

DAMAGE & WEAR AND TEAR.

MC CS due 6.55, partly held as a CS, now completed (at Southampton)
due 2.57 now held

N° 4 P and N° 6 S cylinder liners replaced due to fracture, and their
pistons rods replaced due to cracks in threads of crosshead nuts.
Crosshead bearing replaced from spare.

- N° 1 Diesel generator examined running & found in order.
- Stbd. main engine N° 1 & 2 crankpins & journals examined & found efficient. The surveyor recommends they be again examined before end of 2.57.

It is submitted the vessel is eligible to remain as classed, with record of Survey + LMC.CS 11.55 & as recommended, subject as
TS. CL (p+s) 12.56

recommended, but without reference to N° 1 Diesel generator owners should be informed that the holding down & chocks of both engines, the starboard main engine scavenger blower and N° 10 crankpin, and the evaluator not been surveyed for over four years and should be with at an early date.

now completed, see
Son. Wk. 26-3-57 JG.

now, subject to journals of N° 1 & 2 units being again re-examined the end of February 1957



30

2021

Lloyd's Register
Foundation

31/1/57

1557

JG

1957

8-015354-0017