

Rep. 9.

B.C.

No. 8118

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

19 APR 1950

12- 3- 50

16- 3- 50

Port of

SINGAPORE

Date Survey held at SINGAPORE

Date First Survey 24-2-50 Last Survey 28-2-1950

(No. of Surveys 4)

12637 on the Machinery of the Vessel, DONKEY SCREW SS "HONG ANN"

Gross Tonnage	394	Vessel built at BEVERLEY	By whom COOK, WELTON & GEMMELL, LTD.	When 1945	10
Net Tonnage	112	Engines made at HULL	By whom AMOS - SMITH, LTD.	When 1945	10
Mechanical Horse Power	375 HP	Boilers, when made (Main) 1945	(Donkey) —	When 1945	10
No. of Main Boilers	1/2	Owners THE HO HONG STEAMSHIP CO (1932), LTD.	Port SINGAPORE	Voyage —	
No. of Donkey Boilers	—	Owners' Address —	(as already recorded in Appendix to Register Books)		
Steam Pressure —		Managers —	Particulars of Classification (which may be found in Register Books & Supplements)		
in Main Boiler	200 lbs	If Surveyed & fit for Dry Dock STIRWAY (TANJONG RHU)	Classification	Registration No.	Number and Name (including Admiralty List)
in Donkey Boilers	—	(Date when fit)	For Special Survey	10,45	TS(03) 11,48

Last Report No. Port

Particulars of Examination and Repairs (if any) MBS SURVEY AND B.R.S.

Identified below are what should be reported in detail and precisely in the Report of the Survey. Those clearly the cause of damage, if any, and, in detail, the number and nature of temporary and consequential Repairs. Details on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and Repairs being required in the body of the report, should be briefly summarized at the end of the report. State also the date and duration any Actions respecting this ship.

In Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined —

Was a damage report made by anyone else? If so, by whom? —

Did the Surveyor personally go into each Main Boiler separately and make a thorough examination at this time? Yes

Donkey

If not, state for what reason —

What parts of the Boilers could not be thus thoroughly examined —

Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? —

State latest date of internal examination of each boiler 25th February, 1950

Did the Surveyor examine the Safety Valves of the Main Boilers? Yes

Did the Surveyor examine the Safety Valves of the Donkey Boilers? —

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes

Did the Surveyor examine the drain plugs of the Main Boilers? None fitted

Did the Surveyor examine all the mountings of the Main Boilers? Yes

Has the screw shaft now been down and examined? No

Has the shaft now been changed? — If so, state reasons —

Is an approved oil retaining appliance fitted at the after end? —

Is the shaft now fitted with a continuous babbitt? —

State date of examination of Screw Shaft —

State the wear date of the screw bush 36/1000.

Is electric light and/or power steady? Yes

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Are the parts, when returned to the Surveyor, to be repaired? If so, what arrangements should be made for their return?

If the Surveyor is not complete, state what arrangements have been made for its completion and what remains to be done.

Now done. Noseal placed on slipway. The propeller, stern tube, etc. corrections (opened up)

and their fastenings examined and found in good order.

The main engine cylinders, pistons, steam chest, slide valves; crank and thrust shafts;

the main and auxiliary pumps; the condenser (tested), also the valves, cocks, pipes and

strainers of the pumping arrangements opened up, examined, and all found in good order.

Boiler examined internally and externally together with the safety valves, manholes,

doors and mountings and all found satisfactory. The safety valves were subsequently

adjusted under steam as stated above.

The oil fuel burning arrangements and steam smothering installation examined and

tested under working conditions.

Electrical Equipment. The fittings on the main and sub-distribution switchboards examined, the

electric cables examined, the insulation resistance of the generators (Please see Continuation Sheet)

General Observations, Opinion, and Recommendation. The machinery of this vessel is eligible, in my

opinion, to remain as classed and to have fresh records of MBS* 2,50 and B.M.S. 2,50

to be made in the record of the vessel's machinery in the Register Book, consequent upon this survey, and the any alterations required

to be made in the record of the vessel's machinery, before, working drawings, etc.; thus, for example, 25/2/51, B.M.S. 2,50 M.A.C. 2,50 to type 25/2/51, P.D. 2,50.

Committee's Minute

Last signed

WED. 10 MAY 1950

MBS * 2,50

B.M.S. 2,50

CERTIFICATE WRITTEN.

W.P. Watson
Engineer Surveyor to Lloyd's Register of Shipping



015390-015404-0224 1/2

Insert Character of Ship and Machinery precisely as in the Register Book.

SOCIETY'S SINGAPORE OFFICE.

Is a Certificate required if so, to be sent to

Rpt. No.

Port of SINGAPORE.

Continuation of Report No. 8118 dated 13th March, 1950

S.S "HONG ANN."

cables and other fittings tested and after minor repairs found satisfactory.
The installation examined and tested under working conditions and found
satisfactory.

Wear and tear repairs Circulating pump impellers shaft found badly worn and resurfaced.
Feed pump liner worn and scored, new liner fitted.
Boiler mountings and ship side valves generally overhauled.
Other minor repairs effected.

W.R. Watson.