

To be attached

Recd 11/6/91

"Saint Rognvald"

Aberdeen

4240

June 6th. 1891

George Lyle Hindmarsh

The Owners (The North of Scotland
Orkney, and Shetland Steam Ship Company)
inform the Iron & Steel Chamber
"Saint Rognvald" of Aberdeen
on the thirtieth of March last, and
subsequent dates, will be lying in
the Aberdeen Graving dock, for
the purpose of ascertaining the
amount of damage. Water is
now seen entering through
the vessel sounding on the rocks
off Workhead, near Kirkwall, on
the morning of the twenty third
March last, and remaining until
the evening of the twenty seventh
of March. The holds cabin and
saloon being flooded; with the
exception of the Engine Room.
For particulars see my book
and protest.

On examination the undersigned



© 2021

Lloyd's Register
Foundation

S.S. Saint Rognvald

found the following plates on the starboard side badly indented, or broken: In the garboard stroke, Nos. one, six, eleven, eight, nine, ten, eleven, twelve, fifteen, sixteen, seventeen, eighteen, nine, twenty, twenty-one, and twenty-two plates. In its stroke, Nos. eight, twelve, seventeen, eighteen, nineteen, and twenty plates.

In C stroke Nos. ten, and eleven plates, and number eleven, in D stroke.

The following plates on the starboard side, were also indented, but to a lesser extent than the foregoing.

The first plate in the garboard stroke. In its stroke Nos. nine, ten, eleven, thirteen, and fifteen plates. In C stroke, Nos. twelve, thirteen, fifteen, sixteen, seventeen, eighteen, and nineteen plates.

In D stroke, Nos. twelve, thirteen, and fourteen plates.

On the port side, the following plates were found badly indented, or broken: the twentieth plate in the garboard stroke; the eighteenth in its stroke, and the



© 2021

Lloyd's Register
Foundation

3

St. Saint. Rognvald
Hathaway in C 111.

The following plates on the port side, were also intended, but to a lesser extent, for the starboard stroke. Nos. fourteen, fifteen, sixteen, and nineteen plates. In D stroke, Nos. twelve, and thirteen plates. In C stroke, Nos. eleven, twelve, fourteen, fifteen, sixteen, seventeen, and eighteen plates.

The following lists were started, and examined, on the starboard side, in addition to those, where the plates were damaged. Two in D stroke, two in C stroke, one in D stroke. Five in E stroke, nine in F stroke, seven in G stroke, and eight in the sternbrace.

On the port side, the following lists, were started and examined, in addition to those where the plates were damaged. One in E stroke, two in C stroke, two in D stroke, five in E stroke, six in F stroke, and four in the sternbrace.

St. Saint Rognvald

The midship length of the
starboard bridge deck, shown
up in inches in the illustration,
are marked, and the same
marked. The forward length
of the bridge deck, on the front side,
with piers marked.

Two lengths of keel were
in way of the household, one
knot, six feet, and another
of the keel pins, loose.
In the forehold the
frames, floors, and running
frames, had all broken, as
follows: On the starboard side
the second frame from the
forward engine, from bulkhead
broken; the adjoining four
frames, and reverse four
forward of this also at sea;
and the frames, floors, and
reverse frames, to the third
first frame broken; the
second, second, and twenty
third, frame bent.

The central line is
the forehand, over the cross
amongst gloos set up, and
the longitudinal angle iron.

St. Saint Rognvald
broken, and the rivets scattered.

The side keelson angles, on
the starboard side, in the
forehold broken, forty eight
feet; and two intersecting plates
of same, also broken; the remaining
intersecting plates cracked, and
the angles connecting them broken.
One hold transverse beam
and one bent.

One lower deck beam at the
fore end of the fore hatch bent
and angles of same broken.
One beam at the after end of
the fore hatch broken, and the
beam above this, broken at the
Knee. The second beam from
the hatch, bent, and one half
beam broken.

Two main deck beams broken
and one reverse frame, on the
fore hold between decks.

In the Engine and Boiler
space: the deep floor plates
and frames, on the engine room
bulkhead, broken and badly
shattered. The adjoining engine
reverse frame, and floor all
forward, also broken, and



© 2021

Lloyd's Register
Foundation

56
A.D. Saint Rognvald

In the second frame from the
sternward bow stem. Then on
the starboard side, three frames
under the engine room bulkhead and
fore, amid. and the rivets loose.

On the port side the eighth,
and thirteenth frames, and
floor plates, forward of the
engine Room bulkhead, broken.
The fourteenth frame, and
the next seven frames, in
many of the boilers broken.

In the after hold. The two
leaving and stop valves, and one
steel spar hammer broken, with
plain bent and rivets slack.

The second, third, fourth,
fifth, sixth, and seventh frames,
abreast the Engine Room bulkhead,
broken; the eighth frame, floor plate,
and reverse frame, broken; the
ninth, and tenth frames, broken,
and from the eleventh, to the
nineteenth frame, inclusive
the frames, floor plates, and
reverse frames found broken.
The twentieth frame broken,
the seventyfirst, to the seventyfourth
frame, bent, and rivets missing.



© 2021

Lloyd's Register
6/12
0131+12

7

S.S. Saint Reginald*

James runs inבעמגער
and rudder stock. The crosshead
and pin, for steering gear, also
broken.

The decks strained. The cabin, and
saloon fittings, more or less damaged
through immersion, and the
straining after vessel.

The propeller blades broken,
and the shaft damaged, and
blown.

Recommended that the
above mentioned broken, or
badly indented plates, be removed,
viz: on the starboard side: sixteen
plates in the port and starboard
lift plates, in 15 strokes, four
plates in 2 strokes, and one
in 1 stroke; and the following
plates, to be taken off, forward
spair, and port bow, viz: in
the starboard stroke, four in
15 strokes, six in 2 strokes, and
three in 1 stroke.

The above mentioned plates
broken, or badly indented, on
the port side, to be removed, viz
one plate in the starboard stroke,
one in 15 strokes, and one in 2 strokes
and the following plates to be
removed, viz:

St. L. Sainte Rosevald

down off forward, pointed, and put back. Two plates in the garboard strake. Seven in C strake, one of the inner not being satisfactory after pairing, was removed.

Two plates in the garboard strake, and two in the adjoining strake. All the paired in place.

The following, Luther holes, reinserted:—
on the Starboard side:—Two in B strake,
two in C strake, one in D strake, five
in E strake, nine in F strake,
seven in G strake, and eight
in the Sternstrake.

On the port side, one in B strake,
two in C strake, and two in D strake,
one in E strake, six in F strake, and four
in the Sternstrake.

The midship length of the
starboard bilge keel, forty feet in
length, holes taken off,
surfaced, paired, and put back;
and the downward length on the
port side, to be removed.

In lengths of keel in way of
the forehold, hole removed and
retightened, and put back, and
the keel rivets holes removed
where placed in the remaining lengths.

S. J. Saint Rognvald

The main girders, plates and hole
holes ~~the~~ *S. J. Saint Rognvald*.
Tin plate in the hold,
holes removed, on the starboard
side, from the middle line to the
bulge, and two holes partly
removed, and the broken frames
and, reverse frames, hole partly
removed, and fitted with suitable
pieces at the back.

The central main keelson made
joined, and the longitudinal
angle irons for same, hole
reduced, and fitted with a
long baron piece.

The side keelson angle irons
on the starboard side, in the hold,
holes removed; forty eight
feet. Two intermediate plates
for same, and six angles. hole
removed, and the remaining
intermediate plates, for this portion
of the keelson, hole taken out
straightened, and put back.

The hold stanchion, hole, removed,
one hole taken out, and straightened
and two, removed for repairs to been
holes put back.

Four lower deck beams. hole
cut, and partly removed, and angle iron
for same, and one half beam hole



© 2021

Lloyd's Register
Foundation

S.S. Saint. Rognvald*

taken out, mended, and replaced.

The main deck beam known to
be doubled, and one broken main
beam hole also doubled.

In the Engine and Boiler
space. The deep floor plate, or the
Engine Room bulkhead, and the
frames for same, holes partly
removed. The adjoining frames
floor plate, and several beams,
also to be partly renewed, and
the second floor, hole filled
with a packing piece, where
broken. Three frames ~~and~~
the Engine, hole partly renewed,
and fair hole wired, and
partly renewed.

In the spot inside the bulkhead
and thickness floor plate down
of the Engine Room bulkhead, hole
filled with double beam, where
broken, and the ten broken
frames also filled with double
pieces.

In the after hold the three
cating holes strengthened, by fitting
a double plate, and bracket plates
between the two plates, and the
door rivets to be renewed.

S.S. Saint Rognwald

The Captain found of general damage:
Holes holed, and the iron plates
removed, where started.

Nineteen frames, and ten floor
plates, holes cut and partly removed.
Four courses frames, holes double,
and six frames, to be repaired, and
partly removed.

The deckhouse rivets in the
sternpost, were redone; holes removed;
a new crosshead, and pin, to
steering gear, all to be replaced by
the fitter, holes filled; for
examination of plates, and
steering gear hole overhauled.

The decks holes repaired,
and the cabin, and saloon, fittings
holes made good, and the vessel
holes scraped, and painted inside
and outside.

Giving to the vessel damage
were considerably stored in, the
stoker below the sternpost
on each side, was recommended
holes doubled, from the forecastle
to about the deck to the ports.

Two propeller blades to be
removed. The thrust pins
placed in the lathes, and the

S. & J. Saint Roanwald
whole outfit sailing, have been up.
In consequence of the adverse
seas. The bedding on each tier
was removed, and afterwards
replaced. The hatchways, and
hatches, however, and the main
and deck, cushion strips, have
remained, and afterwards repainted.

The fittings of the cabin, lights,
radio telephone, were unharmed, and
air vent. where necessary; including
cables, safety pens, switches, joint
boxes, lamps, and lampshades.

The main cables leading to the
saloon, and fore cabin, having
been severed, proper insulation
was made; in order that
the vessel, and her fittings, may
be placed in as good and efficient
condition, as before sustaining
the damage in question.

See E 10-10-0

G. L. Friendman
Appended is a list of stores and fittings
that have been lost or damaged
through the storming in question.