

No. 135 Survey held at Brixham - - - Date 21 October 1837
 265 on the Schooner, North Ash - - - Master Richard Sprague
 94 Tonnage 95 050 Built at Brixham - - - When built, year 1810
 By whom built Capt. John Lane - - - Owners Henry J Dugdall & Co. Brixham
 Port belonging to Brixham, Port of Dartmouth Destined Voyage Brixham to Cardiff in Wales
 If Surveyed Afloat, or in Dry Dock Surveyed often on the Blocks, during progress of repair, and also
 See Plymouth Survey No 82. classed as a boat in Brixham Pier.

Length aloft	Feet	Inches	Length	Feet	Inches	Length	Feet	Inches
	63	9	Extreme Breadth	17	7	Depth of Hold	11	5

Scantlings of Timber.

Timber and Space	each	inches	Middle	inches	Ends
Floors	sided	11	Moulded	11	10
1 st Foothooks	"	9	"	9	
2 nd Ditto	"	7 $\frac{1}{2}$	"	7 $\frac{1}{2}$	7
3 rd Ditto	"	6 $\frac{1}{2}$	"	6 $\frac{1}{2}$	6
Top Timbers	"	6	"	6	6
Deck Beams	Number of	19	"	9	9
Hold Beams	No. Da	2	"	9	9
Keel	"	10 $\frac{1}{2}$	"	14	-
Kelsons	44 feet in length	"	14	"	18

Thickness of Plank.

Outside.	inches.	Inside.	inches.	
Keel to Bilge	Elm	2 $\frac{1}{4}$	Foot Waling	3
Bilge Planks		4	Bilge Planks	4
Bilge to Wales	Oak	2 $\frac{1}{4}$	Ceiling in Flat	2 $\frac{1}{4}$
Wales	do	4	Ditto Bilge to Clamp	2 $\frac{1}{4}$
Topsides	do	2	Hold Beam Clamps	-
Sheer Strakes	do	3	Deck Beam Ditto	3
Plank Sheers	do	3	Ceiling 'twixt Decks	2
Water-ways	do	4	Hold Beam Shelves	-
Upper Deck	yellow pine	2 $\frac{1}{2}$	Deck Beam ditto	-

Size of Bolts in Fastenings.

Copper.	Iron	inches.	Iron.	inches.
Heel-Knee, and Dead Wood abaft	1 $\frac{1}{8}$		Hold Beam	7/8
Scarps of Keel	N ^o . one		Deck Beam	3/4
Floor Timber Bolts	1 $\frac{1}{8}$			7/8
Kelson ditto	1 $\frac{1}{4}$			
Transoms and throats of Hooks	1 $\frac{1}{8}$		same in Iron above the Copper	{
Arms of Hooks	7/8			

Timbering.—The Space between the Floor Timbers and Lower Foothooks in this Vessel is 2 Inches. The Space between the Top-timbers is 4 Inches. The Stem, Stern Post, Transoms, Aprons, Knight Heads, Hawse Timbers, are composed of Oak timber and are free from all defects.

Her Floors and first Foothooks are composed of Oak Timber.

Her other Foothooks and Top Timbers of d" -

Her Shifts of the first and second Foothooks are not less than 3 feet N.B. When reported by you less than the prescribed Rule, then state how many.

The rest of the Shifts of the Frame are d"

The Frame is well squared from the first Foothook Heads upwards, and free from sap, and from thence downwards, the frame is well squared.

All The alternate Frames are bolted together.

The Butts of the Timbers are quite close together; their thickness not less than of the entire moulding at that place.

The Frame is chocked with Butt at each end of the chock.

The Main Kelson is composed of Oak timber and the False Kelson of Oak -

The Scarps of the Kelsons are not less than feet inches in one piece

The Deck and Hold Beams are composed of Oak

Planking Outside.—This Vessel's Plank from the Keel to the first Foothook Heads is composed of English Elm -

From the first Foothook Heads to the Light Water Mark of Oak timber

From the Light Water Mark to the Wales of d"

The Wales and Black-strokes are of d"

The Topsides of d"

The Sheer-strokes of d"

The Gunwales of Oak timber Water-ways of

The Shifts of the Planking are not less than feet inches N.B. If reported less than the prescribed Rule, state whether general or partial, and if partial, in what part of the Ship.

The Planking is wrought between.

Planking Inside.—The Clamps are composed of Oak the Stringers of

The Bilge Planks of Oak and the remainder of the Ceiling of

Fastenings.—To Hold Beams — Oak Lodging knees well bolted & secured

Deck Beams d" — d" double kneed -

Number of Breasthooks four Pointers Crutches

Butts End Bolts are of 3/8 Iron in the Bottom, and one Bolt in each Butt End through and clenched.

Bilge and Footwaling bolted through and clenched.

General Quality of Workmanship very good -

We certify that the preceding is a correct description of the above-named Vessel.

Builder's Name (on present repairs)

Surveyor's Name

Robert Burneau
Ch. Burneau
Harris Jones
© 2021
Lloyd's Register Foundation

new Fore Mast. Bowsprit & jib boom — new Chains hoisted up to both Standing Bowsprit - no head
new Fore Yard & Main gaff — mast.

Her Masts, Yards, &c. are in very good condition, and sufficient in size and length.

She has SAILS.

N°.		Fathoms.	Feet	Inches.	N°.
2	Fore Sails, one of d°, new	17.5	2 Chains 80-1-95 f.	18 7/8	3
2	Fore Top Sails, — d° —	7.5	1 Chain Stream	6 1/2	1
2	Fore Topgallant Sails d° —	8.0	Hempen Stream Cable new	6 1/2	2
2	Fore Topgallant Stay Sails, d° —	8.0	Hawser half worn	6 1/2	
2	Main Sails, — — — — —	—	Towlines	—	
1	Main Top Sails, new	28.0	Warp 3:4 & 4 1/2 good	—	
and	1 new Square sail 2 Standing Flying Jib on new 2 Studding Sails	—	All of the best quality.	—	

Her Standing and Running Rigging is in very good order sufficient in size and good in quality.

She has one new Long Boat and one jolly boat in good repair, both clinthwork built

The present state of the Windlass is good order Captain a good iron and Rudder new, — in very good Sound State, with present Palls, Rising Chock &c.

General Remarks—Statement and Date of Repairs.

This Vessel has been haul'd up at the higher part of Brixham Pier, and has undergone a very extensive repair — mainly rebuilt, as per Ship builder's Certificate here annexed. — I have surveyed or inspected said repairs weekly during it's progress from it's commencement to the completion all defective timbers & planks has been replaced new — done with good materials — & good workmanship.

I consider her to have had the repairs & work done as required by the Rules laid down by the Committee for restoration of Character to the first letter — for at least the period of six years & is now in a high state of repair & efficiency calculated to carry any dry & perishable cargo nearly equal to any new vessel —

She has been upwards of 14 Months under said repair — the Skip wrights note including the Smith's note exceeds £700.

If Sheathed, Doubled, or Felted, single bottom

and Date when last done

And I am of opinion this Vessel should be Clasped 6 A. N. 1

fe 120 The Amount of the Fee.....£ 1 : 1 : 0 is received by me,

Committee Minute

24 Oct 1837

Character assigned

Repaired & A 1 for 6 years

© 2021

Lloyd's Register Foundation