

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, 16th Nov. 82.)

5903
in Survey held at *Glasgow*
Book. *192* on the *Iron S.S. "Fire Queen"*
Date, first Survey *31st August* Last Survey *11th November 1882*
(No. of visits *19*) Master
YEAR. MONTH.
Tonnage under Tonnage Deck *697*
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Or. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage *1172*
Crew Space, as per Rule
Register Tonnage, cut on Beam
Engine Room
Reg. Tons as St' mer, cut on Bm. *797*
Built at *Hartlepool* When built *1864*
Owners *W. Banks* Port belonging to *Liverpool*
Residence *134 Queens Gate, London; 46 Place Vendome, Paris*
By whom built *Pile Spence & Co.* Destined Voyage
If Surveyed Afloat or in Dry Dock *Afloat*
(State Name of Dock)
Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.
Last Survey, No. *241* Port *Red* Classified *B. 1.*
REPAIRS, OR EXAMINATION AS PER RULE *Renewal of Boilers & Repairs.* *S.S. Cpn. No. 3. '80* *5.81.*
Cause of Repairs to be clearly stated. *Spar deck*

The boilers removed, the whole of the close ceiling in the cargo holds lifted, the iron work of the hull chipped and scraped, and the cement under the boilers removed.

The floors under the engines and in the after hold were found to be much scored and wasted and the watercourses considerably enlarged. We recommended that these should be made good by doubling or by fitting a sufficient number of efficient intercostal plates between the wasted floors. This the Owner declines to do (see letters attached to this report)

The floors, frames, reverse frames and intercostal keelson plates under the boilers, all more or less considerably wasted, are now being repaired although not in a manner considered satisfactory by us, the doubling plates to the floors not nearly extending out to the end

Present Condition of the		
Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables ranged <i>240 fms</i>
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper (or Y.M.) When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		
Hatches		
General Observations, Opinion as to Class, &c.		

In consequence of the Owner declining to repair the floors under the engines and in the after hold as recommended, and which we consider to be necessary for the vessel to retain her class, we have withdrawn from the survey, and submit the foregoing for the consideration of the Committee.

The Amount of Entry Fee ... £ : :
Special ... £ *6: 6: 0* received by me, *188*
Certificate (if required) } £ : :
to be sent as per margin... }
(Travelling Expenses, if any, £)
Committee's Minute
Let of cargo 17/11/82
Character assigned
Expenses Character with Lloyd's Register
22/11/82
23/11/82

5903 gls

the wasted parts, as recommended. The plating of the stern
and bow, between decks, and more especially under the
sidelights is wasted away considerably - but the Emperor
has not decided as yet what course he will take with these.

G. Stanley
J. W. Thompson



© 2019

Lloyd's Register
Foundation