

# Report of Survey for Repairs, &c., of Engines & Boilers.

No. *9014* Date of Writing Report *8<sup>th</sup> Feb.* 188*9* Port of *Glasgow*  
 No. in Reg. Book. Survey held at *Glasgow* Date, first Survey *29<sup>th</sup> Jan<sup>y</sup>* Last Survey *7<sup>th</sup> Feb.* 188*9*.  
*807.* on the Machinery of the *S. S. Brammore* Master *Thomas Whipp* No. of Visits *6*  
 Tonnage { Gross *833.* Net *419.* Vessel built at *Renfrew* By whom *W. Simons & Co* When *1881-4*  
 Registered Horse Power *180.* Engines made at *Renfrew* When *1881* Boilers, when made (Main) *1881* (Donkey) *1888*.  
 No. of Main Boilers *2.* Owners *Clyde Shipping Co.* Port *Glasgow* Voyage *Crossing*  
 Steam Pressure in Main Boilers *95 lbs* If Surveyed Afloat & in Dry Dock *Anglis Slipway.* Class of Vessel & Machinery *100 A*  
 in Donkey Boiler *60 lbs* (State name of Dock.) (as in Register Book.)

Last Survey No. *11. 87.* Port *Glasgow*  
*T. L. M. C. 11. 87.*

Particulars of Examination and Repairs (if any) *S. S. No 2.*  
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time? *Yes*  
 If this was not done, state for what reasons? *-*

And what parts of the Boilers could not be thus thoroughly examined? *-*

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler? *-*

When this vessel was on slipway the propeller shaft was drawn in and found in fair condition. Propeller refitted and properly secured.  
 All sea cocks and chests overhauled and examined.  
 The engines have all been opened up, working parts adjusted, and everything found in good condition.  
 The main boilers examined throughout and, after being properly sealed and cleaned, found in good condition.  
 Safety valves overhauled and adjusted.  
 The donkey boiler, which was only fitted last year examined and along with its mountings found in good order.

General Observations, Opinion, and Recommendation:— *This vessel's machinery is now in my opinion in a good and efficient working condition and eligible to be noted in the Society's Register Book: T. L. M. C. 2. 89.*  
 (State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey.)

Office or Registration Fee (per Sec. 27).....	£ : :	Fees applied for
Survey Fee (per Section 25).....	£ 3 : 3	<i>12/2</i> 188 <i>9</i>
Special Damage, Fee (per Section 28).....	£ : :	Received by me, <i>10/2</i> 188 <i>9</i>
Certificate (if required) as per margin.....	£ : :	
Travelling Expenses (if chargeable).....	£ : :	

Committee's Minute *TUES 19 FEB 1889*  
 Assigned *+ Dub 2/89*  
*John Sanderson*  
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.  
*Glasgow*



9014 GL

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that this  
vessel is eligible to  
have L.N.C. 289  
recorded.  
W.A.  
18-2-89



© 2019

Lloyd's Register  
Foundation

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.