

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 11643 Date of Writing Report 14th July 1892 Port of Glasgow (Received at London Office 20 JUL 92)

No. in Reg. Book 199 Survey held at Glasgow Date, first Survey 16th May Last Survey 11th July 1892

on the Machinery of the S.S. Behera. Master Gray No. of Visits 16

Tonnage Gross 1384 Net 829 Vessel built at Newcastle By whom Marshall Bros When 1864 2

Registered Horse Power 127 Engines made at Samberton When 79 Boilers, when made (Main) 79 (Donkey) 79

No. of Main Boilers 2 Owners MacLay & McIntyre Port Glasgow Voyage Spain

Team Pressure in Main Boilers 64 lbs If Surveyed Afloat or in Dry Dock (State name of Dock) _____ Class of Vessel & Machinery B1

Donkey Boiler _____ (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) 8.90
3.5792.97.

Last Survey No. 10854 Port Gls

Particulars of Examination and Repairs (if any)

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes

Do. " Donkey " " " " " no

If this was not done, state for what reasons? donkey boiler removed out of the ship

And what parts of the Boilers could not be thus thoroughly examined? _____

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? _____

Did the Surveyor examine the Safety Valves of the Main Boiler? yes

At what pressure were they afterwards adjusted under steam? 64 lbs.

Did the Surveyor examine the Safety Valves of Donkey Boiler? no

To what pressure were they afterwards adjusted? _____

When the vessel was in drydock all the sea connections were overhauled and examined. Propeller-shaft drawn in and found in good order.

The various parts of the engines such as pistons, valves, rods, valve gear have been sent to the shops and put in good order. New thrust block and bilge pumps have been fitted and all working parts adjusted.

The main boilers have been retubed and a number of corroded stays in the steam space have been renewed and the boilers touched up where required. Boilers tested under hydraulic pressure and afterwards under steam when the safety valves were adjusted to working pressure.

General Observations, Opinion, and Recommendation:— This vessel's machinery is now in my opinion in good working order and eligible to be noted: L.M.C. 7.92. in the Society's Register Book.

Office or Registration Fee (per Sec. 27)	£ :	Fees applied for
Survey Fee (per Section 28)	£ 4 : 00	<u>15/4</u> 1892
Special Damage Fee (per Section 28)	£ :	Received by me,
Travelling Expenses (if chargeable)	£ :	<u>19/4</u> 1892

John Anderson
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required _____

Committee's Minute FRI 22 JUL 1892

Assigned L.M.C. 7.92



FORM NO. 10 - FEBRUARY 1892

Insert Character of Ship and Machinery precisely as in the Register Book.

Report of Survey for Repairs &c. of Engines and Boilers.

[Faint, mostly illegible handwritten text, likely bleed-through from the reverse side of the page.]

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

11643.92

Some slight repairs have been made
the engine & boiler retorted good
some repairs executed - all
on receipt of beam & floor.

[Handwritten signature]
20-7-92



© 2019
Lloyd's Register
Foundation

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.