

Report of Survey for Repairs, &c., of Engines and Boilers.

11843
28 OCT 92

No. 11843 Date of Writing Report 22nd Oct 1892 Port of Glasgow
 No. in Reg. Book 4 Survey held at Glasgow Date, first Survey 12th Oct Last Survey 22nd Oct 1892
 on the Machinery of the S.S. "B. Kemény" Master [Signature] No. of Visits
 Tonnage { Gross 1129 Vessel built at Dumbarton By whom Burrell & Son When 1881 YEAR. MONTH.
 Net 967 Engines made at Dumbarton When 81 Boilers, when made (Main) 81 (Donkey) 81
 Registered Horse Power 130 Owners Reg. Hung. Sea Nav. Co Port Fiume Voyage Fiume
 No. of Main Boilers 2 Surveyed Afloat in Dock Harbour of Glw Class of Vessel & Machinery 100 A 1
 Steam Pressure in Main Boilers 80 lbs in Donkey Boiler 50 lbs (State name of Dock.)
 Last Survey No. _____ Port _____ (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) S. 5723. 11. 91

Particulars of Examination and Repairs (if any) Annual Boiler Survey. L.M.C. 11. 91.
 (State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes
 Do. " Donkey " " " yes
 If this was not done, state for what reasons? -
 And what parts of the Boilers could not be thus thoroughly examined? -
 Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? -
 Did the Surveyor examine the Safety Valves of the Main Boiler? yes
 At what pressure were they afterwards adjusted under steam? 80 lbs
 Did the Surveyor examine the Safety Valves of Donkey Boiler? yes
 To what pressure were they afterwards adjusted? 45 lbs only required

The main boilers have been opened up and examined over all parts and found in good order with the exception of the whole of the top plates of furnaces which were somewhat corroded and out of shape. These have all been renewed and the boilers were afterwards tested under hyd. pressure to 120 lbs and found tight.
 Donkey boiler examined and found in fair order.
 Main & donkey safety valves adjusted under steam as above.

General Observations, Opinion, and Recommendation:— This vessel's machinery appears to be in good order and is in my opinion eligible to remain as classed with the notation of: B.S. 10. 92. in the Society's Register Book.
 (State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1, 91, B.S. 2, 91, or L.M.C. 1, 91, as the case may be.)

Office or Registration Fee (per Sec. 27) £ - - - Fees applied for
 Survey Fee (per Section 28) £ 2 : 10 : - 22/10/1892
 Special Damage Fee (per Section 28) £ - - -
 Travelling Expenses (if chargeable) £ - - -
 *State if Certificate is required Yes
 Committee's Minute TUES 1 NOV 1892
 Assigned B.S. 10, 92

John Sanderson
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

FRI 6 JAN 1893



16-L. E. H. Form No. 9. Trans. or Imp. 5,000, 18/9/91
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 *Certificate.
 The Surveyors are requested not to write on or below the space for Committee's Minute.
 MACHINERY CERTIFICATE WRITTEN.

Insert Character of Ship and Machinery precisely as in the Register Book.

11843 ges

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that this vessel is a duplicate of the one built at ...

*12.8.10.92
On account of corrosion
the furnace crowns have
all been renewed.
C.G.S.
28 10 92*



© 2019
Lloyd's Register
Foundation