

Report of Survey for Repairs, &c., of Engines and Boilers.

MON. 23 OCT 1893

Date of writing Report Oct 26th 1893 When handed in at Local Office Clayton is Port of Clayton

No. in 14 Survey held at Clayton Date, First Survey 3rd July Last Survey 14th Oct 1893

on the Machinery of the Wood, Iron S. V. Dunfield Master R. Russell

Tonnage { Gross 1158 Vessel built at Clayton By whom R. Phipps When 1878-8
 Net 742 Engines made at " When 1878 Boilers, when made (Main 1878 (Donkey)
 Registered Horse Power 100 Owners L. Clark Port Clayton Voyage Coasting
 No. of Main Boilers 2 Surveyed Afloat or in Dry Dock Both Particulars of Classification (which must be inserted
 in Main Boilers 60 lbs (State name of Dock.) Lyth precisely as in Register Book & Supplements.)
 in Donkey Boiler 40 lbs

Last Survey No. 100 Port Clayton

Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Engine opened up and all the working parts taken asunder and overhauled, Crank Shaft & Bearings overhauled. Propeller, Shaft drawn & Stern tube fitted with new wood. Pump & pipes & connections red throughout.

Main Boiler, fitted with set of new tubes. Several Steam Space Stays renewed & a few additional Screw Stays fitted in Combustion Chamber furnaces which were somewhat wasted & laminated at places have been patched where necessary. Donkey Boiler taken out of vessel and overhauled & examined.

On completion of the above repairs the Main Boilers were tested by Hydraulic pressure to 100 lbs. & the Donkey Boiler to 60 lbs.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 9, B.M.S. 9, or L.M.C. 9, as the case may be.)

The machinery & boilers of this vessel have been satisfactorily repaired and are now in good working condition & reliable in our opinion to be noted in the Register Book + L.M.C. 10/93

Office or Registration Fee (per Sec. 27) £ : : Fees applied for 3/10/1893

Survey Fee (per Section 28) £ 4 : : P. 4/4/93

Special ~~Survey~~ Fee (per Section 28) £ : : Received by me, 9/10/1893

Travelling Expenses (if chargeable) £ : : James Mollan Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

* State if Certificate is required Yes WRITTEN. Clyde District

Committee's Minute TUES. 24 OCT 1893

Assigned L.M.C. 10.93

