

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office) THURS. 11 JAN 1894

Date of writing Report 9th Jan 1894 When handed in at Local Office 18 Port of Glasgow
 No. in Reg. Book. 364 Survey held at Glasgow Date, First Survey 12th Dec 1893 Last Survey 6th Jan 1894
 on the Machinery of the Wood, Iron or Steel "Nestia" Master Kainnie
 Tonnage { Gross 3790 Net 2424 Vessel built at Sunderland By whom Doxford & Son When 1890. 3
 Registered Horse Power 450 Engines made at do When '90 Boilers, when made (Main) '90 (Donkey) '90
 No. of Main Boilers 2 Owners Donaldson Brog. Port Glasgow Voyage No. America
 Steam Pressure in Main Boilers 160 lbs If Surveyed Afloat Y in Dry Dock Gwan Dk Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned. (Special Visits). (Machinery and Boiler Surveys (including date of N.B., if any)).
-100 A1 4.93.	-1. L.M.C. 3.90

Last Survey No. _____ Port _____
 Particulars of Examination and Repairs (if any) S.S. No 1

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes
 Do. " Donkey " " " yes
 If this was not done, state for what reasons? _____
 And what parts of the Boilers could not be thus thoroughly examined? _____
 Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? _____
 Did the Surveyor examine the Safety Valves of the Main Boiler? yes
 At what pressure were they afterwards adjusted under steam? 160 lbs
 Did the Surveyor examine the Safety Valves of Donkey Boiler? yes
 To what pressure were they afterwards adjusted? blowing at 95 lbs
 If the Survey is not complete state what arrangements have been made for its completion? _____

All parts of machinery opened and thus were examined: cylinders, pistons valves and rods. Crank and tunnel shafting and all pumps overhauled and working parts adjusted. — When the vessel was in dry dock all the sea cocks were overhauled. Propeller and fastenings found in good condition. (Shaft drawn last docking) —
 The main and donkey boilers found in very good condition, safety-valves adjusted as above. —

General Observations, Opinion, and Recommendation: — This vessel's machinery
(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 0,02, B.&M.S. 0,02 or L.M.C. 0,02, as the case may be.)
is now in our opinion in good and efficient working order and eligible to be noted: -1- L.M.C. 1.94. — in the Society's Register Book. —

Office or Registration Fee (per Sec. 27) £ : :
 Survey Fee (per Section 28) £ 5:10 : :
 Special Damage Fee (per Section 28) £ : :
 Travelling Expenses (if chargeable) £ : :
 Fees applied for 9/11 1894
 Received by me, 10/11 1894

John Sanderson R. L. Dewitt
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required _____
 Committee's Minute _____
 Assigned + L.M.C. 1.94

FRI 12 JAN 1894



16-LRPH-Form No. 9—Transfer Link—10/000, 20/1/93.
 *Certificate to be sent to...
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 Insert Character of Ship and Machinery precisely as in the Register Book.

12669 slls

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD + L.M.C. 1-94

M.A.
11-1-94

[Faint, mostly illegible handwritten text, likely bleed-through from the reverse side of the page.]



© 2019
Lloyd's Register
Foundation

THE SUBSTANTIAL AND LEGIBLE IS NOT TO WRITE