

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18 When handed in at Local Office 18 Port of Glasgow
 No. in Reg. Book Survey held at Glasgow Date, First Survey 23 March Last Survey 2 April 1894
 on the Wood, Iron or Steel Steamer "Cornelian" Master Walter

TONNAGE:— Built at Glasgow By whom Scott & Co. When 1890 3
 GROSS 1108 Owners H. Robertson Port belonging to Glasgow
 UNDER DK. 286 Owners' Address
 NET 139 (If not already recorded in Appendix to Register Book.)
 Surveyed Afloat or in Dry Dock? Ship Name of Dock Belwinburgh Destined Voyage Boating
 WB=DBa tons; f tons; uE&B tons; CellDB tons;
 FPT 26 tons; APT tons; MT tons.
 N.B.—All alterations in the existing records should be underlined.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER: X for Special Survey; Date of last Survey and of Periodical Survey.	Years Assigned now expired	Machinery and Boiler Surveys (including date of N.B., if any).
<u>+100A.1</u> <u>S. 92</u>		<u>+L.M.C.</u> <u>1.90</u>

Last Survey, No. 115218 Port Glasgow
 (Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)
 Society's Freeboard (if assigned) as painted on Ship and now verified } 2 ft. 10 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage through collision with the steamer "Hare" on the 22nd March 1894. & Special Survey No. 1.
Damage Repairs— On starboard side abreast fore rigging one plate of sheer stake renewed; two plates in stake below sheer stake and two plates in the second stake below sheer stake taken off set fair and replaced, one plate in stake below sheer and one plate in the 3rd stake below sheer set fair in place; about 25ft of wood belting with face plate and the angles renewed, one stringer plate renewed, one deck plate set fair in place, one length of gunwale angle renewed, nine frame angles part renewed from keel to gunwale, four frame angles set fair in place, the upper bridge stringer set fair in place for a length of 20ft; two beam ends renewed and new plate knees to same, three beam ends set fair in place and new plate knees to same, one bulwark plate taken off set fair & replaced the iron rail and mouldings to same set fair. The after boat davits straightened and refitted.

SUMMARY OF DAMAGE REPAIRS:— 6 Plates, Faired or Repaired; Frames, ditto. 1 Plates, Renewed; Frames, ditto. Other Repairs 1 stringer, 5 beams, bulwark keel

PRESENT CONDITION OF THE

Decks <u>Good</u>	Transoms, Pointers, & Crutches <u>Good</u>	Copper, or Y.M. <input checked="" type="checkbox"/>	Hatches <u>Good</u>
Waterways	Timbers of Frame at the openings	(State if on Felt.) When put on, Month Year	Boats
Coamings	Ditto ditto at other places	Rudder <u>Good</u>	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings	Keelsons	Windlass & Capstan	Condition, how ascertained <u>by examⁿ</u>
Low'r Dk. Beams & Fastenings	Clamps, Shalvs & Stringers	Pumps	Sails <u>Good</u>
Plating	Sailing (State if examined.)	Engine Room Skylights	Equipment letter
Planking	Ceiling	Coal Bunker, Open'gs, Lids, &c.	Anchors, No. of <u>20 15 1K</u>
Nails or Rivets	Cement or Asphalt (State which.)	Scuppers	Cables (State if now ranged) <u>no</u>
Breasthooks & Stemson	Tanks <u>5.1.7 tested</u>	Cargo & Main H'tch'wys	" length size
	Caulking of Bot'm, D'k, & Wat'r'wys		" Rule length size
			Hawsers & Warps <u>Good</u>
			Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—
 State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptnD91, &c."
This vessel is in a good and efficient condition and in my opinion eligible to remain as classed and to have record of survey H. 94 and the notations of S. G. G. L. No. 1. 94

Office Fee (if chargeable) per Scale II., Sec. 27 £ : : Fees applied for, 6/4 18 94
 Survey Fee (per Section 25) modified £ 2 : 10 : " }
 Special Damage or Repair Fee (if any) (per Sec. 25) £ 3 : 3 : " }
 Travelling Expenses (if chargeable) £ : : }
 Second Surveyor's Fee (if any) £ : : }
 Received by me, H. Sand
 Surveyor to Lloyd's Register of British & Foreign Shipping.

*Is Certificate now required?
 Committee's Minute
 Character assigned +L.M.C. 3.94
100A.1 S. 92
as no. 1-94
 FRI 13 APR 1894
 © 2019 Lloyd's Register Foundation
 GLS 169-0298 (1/12)

Is a Report also sent to the Machinery of the Ship? If not, state whether, and when, one will be sent?
 * Certificate, if required, to be sent to...
 Form No. 2 for Repairs—205.—L.R.P.H.—10,000.—28, 10/93.—Transfer Ink.
 (The Surveyors are requested not to apply on or below the space for Committee's Minute.)

Examination for S. S. No. 1 - Bessel has been placed on shipway
the holds, peaks and bunkers cleared, the timbers and ceiling in
excess of requirements removed fore and aft on each side of vessel
examination made in hold, peaks and bunkers also under boiler
and boilers, fore peak tank tested by water pressure, examination
made of the pumps, valves, equipment, masts and rigging.

Repairs through wear & tear - Several rivets in frames ^{at floors} in way of
fore peak tank renewed, the middle line keelson riveted to floors
in fore peak tank and a deep bracket knee fitted to bulkhead
and middle line keelson in fore peak tank, the cement repaired
fore and aft, three web frames fitted with face plates extending
from hold beam stringer to close ceiling, the frames and plating
above close ceiling has been scaled cleaned and recoated.

N. A. S. J.