

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

11. 118. 12 APR 1894

Date of writing Report 12th March When handed in at Local Office 12th March Port of Glasgow
 No. in Reg. Book. 1072 Survey held at Troon Date, First Survey 12th March Last Survey 29th March 1894
 on the Machinery of the Wood, Iron or Steel S. S. Susannah Kelly Master H. Berant
 Tonnage { Gross 253 Net 91 Vessel built at Belfast By whom M. Hume & Co When 1890 Boilers, when made (Main) 1890 Donkey none
 Registered Horse Power 48 Engines made at Belfast Owners J. Kelly Port Belfast Voyage Belfast
 of Main Boilers one If Surveyed Afloat or in Dry Dock Afloat Dry Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 m Pressure 160
 Main Boilers none

Last Survey No. SS. No 1. Port Damages &
 Particulars of Examination and Repairs (if any) SS. No 1.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes found it satisfactory

Do. " Donkey " " " " none

this was not done, state for what reasons? none

And what parts of the Boilers could not be thus thoroughly examined? none

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? yes found them satisfactory

Did the Surveyor examine the Safety Valves of the Main Boiler? 160 lbs

At what pressure were they afterwards adjusted under steam? none

Did the Surveyor examine the Safety Valves of Donkey Boiler? none

To what pressure were they afterwards adjusted? none

If the Survey is not complete state what arrangements have been made for its completion?

On account of damage all parts of the engines were opened out. The tailshaft drawn & tried in the lathe and the boiler heated to 245 lbs.

Examined the connecting rods & found them good. New lignum vitae has been fitted in the stern tube, the tailshaft has been straightened and new liners fitted & the stuffing replaced in line. Four new propeller blades have been fitted.

Examined the crankshaft, cylinders slide valves & pumps & found them good.

Several stops in the boiler leaked during the hydraulic test. Two of these have been renewed and the rest caulked and fitted with new nuts. Most of the lugs have been expanded.

General Observations, Opinion, and Recommendation:— The machinery of this vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 9, 92, B.&M.S. 9, 92 or L.M.C. 9, 92, as the case may be.)

is now in a safe working condition and eligible in our opinion for the record + L.M.C. 4.94.

Office or Registration Fee (per Sec. 27) £ : : Fees applied for 6/4 1894
 Survey Fee (per Section 28) £ 2:10: :
 Special Damage Fee (per Section 28) £ 2:2: :
 Travelling Expenses (if chargeable) £ 1:8:6 Received by me, 9/4 1894

*State if Certificate is required

Committee's Minute

FRI 13 APR 1894

Assigned

+ L.M.C. 4.94

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

C. E. Brown
 J. M. Sanderson

Lloyd's Register
 Foundation

GLS 169-0295

