

No. 13023

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office)

SAT. 16 JUN 1894

Date of writing Report 18 When handed in at Local Office 18 Port of *Glasgow*  
 No. in Reg. Book. Survey held at *Glasgow* Date, First Survey *15<sup>th</sup> May* Last Survey *11<sup>th</sup> June 1894*  
*260* on the Machinery of the *Wood, Iron or Steel* *S. S. Perth* Master *J. Peckie*  
 Tonnage { Gross *653* Vessel built at *Port Glasgow* By whom *Murdoch & Murray* When *1882 11*  
 Net *395* Engines made at *Dumbarton* When *1881* Boilers, when made (Main) *1882* (Donkey) *1882*  
 Registered Horse Power *80* Owners *J. Rankine &* Port *Glasgow* Voyage *Rotterdam*  
 No. of Main Boilers *1* If Surveyed Afloat or in Dry Dock *Arrossan Dry Dock*  
 Steam Pressure in Main Boilers *70 lbs* (State name of Dock.)  
 in Donkey Boiler *50 lbs*

Last Survey No. *5969* Port *Dundee*Particulars of Examination and Repairs (if any) *+ LMC & Damage*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<i>+100A1</i> <i>12, 91</i> <i>S.P. No. 2-91</i>		<i>+LMC 9.91</i> <i>B.S. 1.93</i>

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *See Dundee Report No. 5969*Do. " Donkey " " " " *Yes* " *"*

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Vessel placed in dry dock, tail shaft drawn in & examined found in good condition, new wood lining fitted in lower part of stern bush. All sea cocks & valves taken adrift, overhauled, and examined, two cocks being refitted on new plates. Propeller & fastenings examined & found in good order.  
 All parts of Machinery viz. Cylinders, pistons, slide valves, pumps etc. opened up & examined, ridges on face of H.P. Cylinder chipped & filed; H.P. Slide Valve taken to shop & planed, & valve face chipped & filed in place. Liner fitted on back of spring behind L.P. Slide Valve H.P. & L.P. Valve spindles cut & new ends welded on. New brass liner fitted on H.P. eccentric straps. New covers fitted on feed pumps. All shafting including Crank shaft uncoupled, examined & tried for truth, found to be in good condition & line. Two new liners fitted in thrust block.

Main Boiler fitted to apply hydraulic test (See Dundee Report No. 5969)

General Observations, Opinion, and Recommendation:— *The Machinery of above*

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 9.92, B.&amp;M.S. 9.92 or L.M.C. 9.92, as the case may be.)

*vessel is now in good condition & eligible in my opinion to remain as classed with new record of L.M.C. 6.94.*

Office or Registration Fee (per Sec. 27) £ : :  
 Survey Fee (per Section 28) £ *3 10* :  
 Special Damage Fee (per Section 28) £ : :  
 Travelling Expenses (if chargeable) £ *2 14* "

Fees applied for

*14/6 1894*

Received by me,

*15/6 1894*

\*State if Certificate is required

Committee's Minute

TUES. 19 JUN 1894

Assigned

*+ LMC 6.94*

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register  
Foundation

GLS170-0087 (1/2)

THE RECORD + L M C 6, 94  
in account of Wear & Tear  
Several moderate repairs  
effected to Boilers & machs  
N.B.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

on account of damage  
Moderate repairs  
effected to Machinery  
& Boilers  
J. R. S.  
16-6-94

[illegible]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN

*S.S. "Perth" of Glasgow*

examined inside furnaces & Combustion Chambers found a bolted Covering Patch on back plate of Star Combustion Chamber Cracked & leaking, on removing this patch found back plate cracked in several places between screwed stays, recommended defective part to be cut out & a rivetted patch to be fitted with four new screwed stays, in Centre Combustion Chamber found 2 screwed stays leaking recommended nuts to be removed stays caulked & new nuts & washers fitted furnace plating at back flanged part wasted & cracked recommended defective part to be cut out & an efficient patch fitted. In Port Combustion Chamber found a small cup bolted Patch on leaky stay the nut being away & stay cut flush & Chamber Plate Cracked, recommended a rivetted washer to be fitted & a new screwed stay with nuts back & front <sup>also two screwed stays leaking to be renewed</sup> The above repairs have all been efficiently carried out, & the boiler afterwards tested by hydraulic Pressure to 105 lbs. when everything was tight & satisfactory. Safety Valves & all other mountings have been overhauled, examined & renewed where required.

Donkey Boiler tested by water Pressure to 55 lbs. when uptake leaked badly, boiler afterwards being opened up & examined found a large blistered hole in back of uptake, recommended defective part to be cut out & an efficient Patch fitted, which is now done. Safety Valve & all mountings overhauled, examined & renewed where necessary.

Steam has been raised on Main & Donkey boilers & their Safety Valves adjusted to safe working pressures, the engines were tried when everything worked satisfactorily.

For Damage. The Shafting was all uncoupled & tested for strength & tail shaft drawn in & examined. The Main & Donkey boilers tested by hydraulic pressure. New Cast Iron Chock fitted under <sup>Main</sup> boiler & boiler securely fastened to vessel, all pipes repaired, renewed & refitted where necessary, donkey pumps bilge & ballast Connections all overhauled cleaned & repaired as required, Platforms gratings, telegraph etc. all renewed & repaired as required & M. & D. boilers recovered with ~~no~~ conducting Composition two new Steam Pressure gauges fitted.