

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office TUES. 26 MAR 1895)

Date of writing Report 18 When handed in at Local Office 18 Port of Glasgow

No. in Reg. Book. Survey held at Glasgow Date, First Survey 13. July Last Survey 12. March 1895

1046 on the Machinery of the Warrior Steel S.S. Strathclyde Master McKenzie

Tonnage Gross 1142 Net 2648 Vessel built at Greenock By whom Russell & Co When 1894-5m

Registered Horse Power 353 Engines made at Port Glasgow When 1894 Boilers, when made (Main 1894 (Donkey) 1894)

No. of Main Boilers 3 Owners Burrell & Son Port Glasgow Voyage India

No. of Donkey Boilers 1 Steam Pressure in Main Boilers 140 lb Surveyed Afloat or in Dry Dock Both (State name of Dock.)

in Donkey Boilers 100

Last Survey No. Port

## Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Year and Month when Surveyed.	Machinery and Boiler Surveys (including date of N.B., if any).
For Special Survey.		
Date of last Survey and of Periodical Surveys.		
	<u>100 A.I. 5/94</u>	<u>+ L.M.C. 5/94</u>

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Yes  
100

✓  
✓  
✓  
✓  
✓  
✓  
✓

✓

In consequence of several of the furnaces in the boilers of this vessel becoming distorted, out of shape, and the metal showing signs of tearing on inner or water side of the furnaces near the strengthening ribs, the starboard furnace of Starboard Boiler has been replaced by a new one and the three furnaces in the Port Boiler replaced by new ones. One or two of the other furnaces slightly set down on the Crowns near to back end but not such as considered necessary to do anything to. On examination found these Boilers otherwise in good order.

On completion of the above repairs the Boilers were tested by Hydraulic pressure to 220 lbs per sq inch.

## General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 4, 04, B.&M.S. 4, 04 or L.M.C. 1, 04, 140 lb., F.D., &c.)

Those repairs have been satisfactorily carried out by Messrs Brown & Wood & Gordon the makers of the Boilers, and they are now in good working condition & reliable in our opinion (the vessel) to remain as classed.

Office or Registration Fee (per Sec. 27).....	£	:	:	Fees applied for
Survey Fee (per Section 28).....	£	:	:	18
Special Damage Fee (per Section 28).....	£	:	:	
Travelling Expenses (if chargeable).....	£	✓	:	Received by me,
				18

\*State if Certificate is required

Committee's Minute

Assigned

FRIDAY 29 MAR 1895

James Morrison, C. & Furdock.  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.  
Glasgow District

Lloyd's Register  
Foundation

GLS 171-0370

State if a Report is also now sent on the ... or if not whether, and when, one will be sent.

Insert Character of Ship and Machinery precisely as in the Register Book.



on account of being damaged  
distressed, 11 miles from Port  
de France have been

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

13552ges

It is submitted that  
this vessel is eligible to  
remain as CLASSED.

Q P R

27-3-95

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019  
Lloyd's Register  
Foundation