

Report of Survey for Repairs, &c., of Engines and Boilers.

FRI. 10 JUN 1898

(Received at London Office)

Date of writing Report 18 When handed in at Local Office 18 Port of *Glasgow*

No. in Reg. Book. *203* Survey held at *Ardrossan* Date, First Survey *2nd June* Last Survey *2nd June, 1898*

on the Machinery of the *Wood, Iron or Steel* *S.S. Beronia* Master *J. Logan*

Tonnage { Gross *1327* Vessel built at *Newcastle* By whom *Palmer & Co. (Ltd.)* When *1879* YEAR. MONTH. 12

Net *840* Engines made at *do* When *1879* Boilers, when made (Main) *1879* Donkey) *1879*

Registered Horse Power *140* Owners *Barnald & Taylor* Port *Glasgow* Voyage *Spain*

No. of Main Boilers *1* If Surveyed Afloat or in Dry Dock *Afloat* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Steam Pressure—*75 lbs* in Main Boilers

in Donkey Boiler *55 lbs* (State name of Dock.)

Last Survey No. *15900* Port *Glasgow*Particulars of Examination and Repairs (if any) *Boiler Survey +100 A1*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ☒

Do.

Donkey

If this was not done, state for what reasons? ☒And what parts of the Boilers could not be thus thoroughly examined? ☒Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ☒Did the Surveyor examine the Safety Valves of the Main Boiler? ☒At what pressure were they afterwards adjusted under steam? ☒Did the Surveyor examine the Safety Valves of Donkey Boiler? ☒To what pressure were they afterwards adjusted? *55 lbs*If the Survey is not complete state what arrangements have been made for its completion? *Complete*

Adjusted donkey boiler safety valves under steam to the above pressure.

General Observations, Opinion, and Recommendation:—*The machinery of this*

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 9,92, B.&M.S. 9,92 or L.M.C. 9,92, as the case may be.)

vessel is, in my opinion, in safe working condition, & eligible to remain as classed with record B.S. 1-98

Office or Registration Fee (per Sec. 27) £ : :

Survey Fee (per Section 28) £ : :

Special Damage Fee (per Section 28) £ : :

Travelling Expenses (if chargeable) £ - 5 -

Fees applied for

8.6. 18 98

Received by me,

9.6. 18 98

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

Committee's Minute

Assigned

TUES. 14 JUN 1898



© 2019

Lloyd's Register

Foundation

GL5181-0108

State if a Report is also now sent on the Ship or if not whether, and when, one will be sent.

*Certificate to be sent to

16-LRPH-Form No. 9—Transfer Ink—5,000,210/93.

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that
this vessel is eligible to
remain as CLASSED.

Handwritten signature

10.6.98

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation