

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18..... When handed in at Local Office 18..... Port of Glasgow
 No. in Reg. Book. Survey held at Glasgow Date, First Survey and Last Survey 21 Oct 1898.
 on the Wood, Iron or Steel SS "Victoria" Master J. Brickton 97-98
 TONNAGE:— Built at Glasgow By whom A. Stephen & Sons When 1887 10
 GROSS 1620 Owners SS Victoria Co. Ltd (MacLay & Co. Intype) Port belonging to Glasgow
 UNDER DECK 1262 Owners' Address
 NET 1022 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Govan St Destined Voyage Bordeaux
 WB=CellDBorDBa 488 feet; uE&B 1 feet; J 1 feet;
 total capacity 20 tons. FPT 20 tons; APT 20 tons; MT 1 tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 15893 Port Glasgow

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarized in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

CHARACTER. For Special Survey, Date of last Survey and of Periodical Surveys.	Year Assigned Surveyed expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>100A1</u>		<u>BS 9.98</u>
<u>1.98</u>		<u>LMC 5.96</u>
<u>SS Class No. 1-96</u>		

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

REPAIRS, and EXAMINATION AS PER RULE, FOR Lighting of bottom after grounding on the bar at Buxton
on August 30th 1898

The vessel placed in dry dock. Bottom cleaned, examined, found to be in good condition, and recoated.

A few rivets in the rudder renewed.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Engine Room Skylights	Boats
Decks <u>Good</u>	Inner Bottom Plating <u>Not seen</u>	Coal Bunkers, Open'gs, Lids, &c. <u>Good</u>	Masts, Heads, &c. <u>Good</u>
Caulking of Decks <u>Good</u>	State if Tanks now tested <u>Not seen</u>	Scuppers <u>Good</u>	Condition, how ascertained <u>From deck</u>
Waterways <u>Good</u>	Bulkheads <u>Good</u>	Cargo Hatchways <u>Good</u>	(State if wedges removed <u>Good</u>)
Coamings <u>Good</u>	Ceiling <u>Good</u>	Hatches <u>Good</u>	Sails <u>Good</u>
Beams & Fastenings <u>Good</u>	Cement or Asphalt <u>Not seen</u>	Planking of Wood Vessels <u>Good</u>	Equipment letter <u>Q</u>
Outside Plating <u>Good</u>	Rudder <u>Good</u>	Treenails ditto	Anchors, No. of <u>3 B-1 S-1 K</u>
Caulking of ditto <u>Good</u>	Windlass <u>Good</u>	Breasthooks & Stems ditto	Cables (State if now ranged) <u>Good</u>
Rivets <u>Good</u>	Have Pumps now been examined and found efficient? <u>Not seen</u>	Transoms, Pointers, & Crutches ditto	" length (on board) <u>Good</u> size
Breasthooks & Crutches <u>Good</u>	Have Sluice Valves now been examined and found efficient? <u>Not seen</u>	Timbers of Frame at openings ditto	" Rule length (per Table 22) <u>Good</u> size
Transoms <u>Good</u>	Have Watertight Doors now been examined and found efficient? <u>Good</u>	Ditto ditto at other places ditto	Hawsers & Warps <u>Good</u>
Frames <u>Good</u>	Have Watertight Doors now been examined and found efficient? <u>Good</u>	Stringers, Clamps & Shells ditto	Standing & Running Rigging <u>Good</u>
Reverse Frames <u>Good</u>	Have Watertight Doors now been examined and found efficient? <u>Good</u>	Salting (State if examined.) ditto	
Floors <u>Good</u>	Have Watertight Doors now been examined and found efficient? <u>Good</u>	Copper, or Y.M. (State if on felt.) ditto	
Keelsons <u>Good</u>	Dblg. Plates under Sounding Pipes <u>Not seen</u>	When put on, Month Year	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.98," or "to remain as classed and to have record of survey, 1.98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel is in good and efficient condition and in my opinion eligible to remain as classed and to have fresh record of survey 10.98


Office Fee (if chargeable) per Scale II., Sec. 27 £	Fees applied for,
Survey Fee (per Section 25) £ 18.....
Special Damage or Repair Fee (if any) £	Received by me,
Travelling Expenses (if chargeable) £ 18.....
Second Surveyor's Fee (if any) £	

Committee's Minute

Character assigned

FRI. 4 NOV 1898

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2020

Lloyd's Register

615187-0172