

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

TUES. 20 JUN 1898

Date of writing Report 16 June 1898 When handed in at Local Office

18

Port of Glasgow

No. in Reg. Book. Survey held at Glasgow

Date, First Survey and Last Survey 14 June 1898

(No. of Visits)

670 on the Machinery of the Wood, Iron or Steel S.S. PRINCESS LOUISE Master

Tonnage Gross 106

Net 17

Vessel built at Glasgow

By whom Ritchie Graham & Milne When 1898 7

Registered Horse Power 370

Engines made at Paisley

When 1898 Boilers, when made (Main) 1898 (Donkey)

No. of Main Boilers 1

Owners A Paterson

Port Glasgow

Voyage Coasting

No. of Donkey Boilers 1

Steam Pressure in Main Boilers 120 lb

Surveyed Afloat or in Dry Dock Helvinkough Slip

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. 16253 Port Glasgow

Particulars of Examination and Repairs (if any) Docking

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years since last survey examined.	Machinery and Boiler Surveys (including date of N.B., if any).
* 100 A I 7.98		* L M C 7.98

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do.

Donkey

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Has the propeller shaft been drawn and examined at this time?

If spare propeller shaft fitted, state whether new?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? 16"

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

This vessel being on the slip the propeller & its fastenings & the fastenings of the sea connections were examined & found to be in good order.

General Observations, Opinion, and Recommendation:— The machinery of this vessel, so far as seen, is in good order & eligible in my opinion to remain as classed without fresh record.

Office or Registration Fee (per Sec. 27) £ : :
Survey Fee (per Section 28) £ : :
Special Damage Fee (per Section 28) £ : :
Travelling Expenses (if chargeable) £ : :

Fees applied for

18

Received by me,

18

State if Certificate is required

Committee's Minute

FRI. 23 JUN 1898

Assigned

H. GARDNER SMITH.
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register
Foundation

GLS184-0208

It is submitted that
this vessel is eligible to
remain as **CLASSED**.

[Handwritten signature]
20/6/99

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation