

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report July 1899 When handed in at Local Office 18 Port of Glasgow THUR. 20 JUL 1899

No. in Reg. Book 434 Survey held at Glasgow Date, First Survey 22 June Last Survey 19 July 1899 (No. of Visits 2)

207 434 on the Machinery of the Wood, Iron or Steel S. S. "STRATHALLAN." Master

Tonnage { Gross 2836 Net 1489 Vessel built at Greenock By whom Russell & Co When 1890 YEAR. MONTH.

Registered Horse Power 335 Engines made at Glasgow When 1890 Boilers, when made (Main) 1890 (Donkey) 1890

No. of Main Boilers 2 Owners Port Voyage Cardiff

No. of Donkey Boilers 1 If Surveyed Afloat or in Dry Dock Dry Dock Govan

Steam Pressure—160 lbs in Main Boilers 80 in Donkey Boilers 80

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER for Special Survey. Date of last Survey and of Periodical Surveys.	Year Assessed how estimated.	Machinery and Boiler Surveys (including date of N.B., if any).
<input checked="" type="checkbox"/> 100 A. 1.		<input checked="" type="checkbox"/> L.M.C. 5.97.
ht Awng. dk. with freebd		
1. 98.		
S. S. Liv. No. 1. 94.		

Last Survey No. PortParticulars of Examination and Repairs (if any) Special Survey

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No.Do. " Donkey " Yes.If this was not done, state for what reasons? Main boiler already done.And what parts of the Boilers could not be thus thoroughly examined? ✓Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓Did the Surveyor examine the Safety Valves of the Main Boiler? No.To what pressure were they afterwards adjusted under steam? 165 lbs.Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes.To what pressure were they afterwards adjusted under steam? 72 lbs.Has the propeller shaft been drawn and examined at this time? YesIf spare propeller shaft fitted, state whether new? New shaft fitted.State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? ✓

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Propeller shaft and sea cocks examined, the sea cocks found good, propeller shaft badly wasted at forward end of after liner, a new shaft has now been made & fitted in vessel.


Donkey boiler & its safety valves examined & found good.

All safety valves adjusted as above.

Examined M.P. guide plate which is cracked for about one third the breadth at centre, it is in good working condition.

All six furnaces have been cut out & renewed with plain furnaces $\frac{3}{4}$ " thick, 3' 1 1/2" diameter & 4' 5" long. - 181 lbs working pressure

Five of the front rings of old furnaces were cracked in corner adjoining front tube plates these have been fitted with doubling pieces. Thus:—



New funnel fitted
Donkey boiler small temporary patch on starboard side combustion chamber renewed with permanent rivetted patch.

Main boilers tested with water to 250 lbs hydraulic pressure

General Observations, Opinion, and Recommendation:— As far as seen the machinery

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9, 97, B.&M.S. 9, 97 or L.M.C. 9, 97, 140 lb., F.D., &c.)

of this vessel is in a good & efficient condition eligible in my opinion to remain as classed & to have fresh record of survey L.M.C. 3.99. noted in the Register Book.

Office or Registration Fee (per Sec. 27)	£	:	:	Fees applied for
Survey Fee (per Section 28)	£	:	:	18
Special Damage Fee (per Section 28)	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	Received by me,
	£	:	:	18

State if Certificate is required

Committee's Minute

Assigned time 3.99

FRI. 21 JUL 1899

FULL CERTIFICATE

WRITTEN 20/7/99

J.W. Dimmock
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



Lloyd's Register
Foundation

Leew shaft renewed on acc given & tear.

All 6 th. B. furnace renewed also funnel & some minor repairs effected.

It is submitted that this vessel is eligible for THE RECORD.

2.7.99

20/7/99

20.7.99

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

[Faint, mostly illegible handwritten text in cursive script, likely bleed-through from the reverse side of the page.]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019
Lloyd's Register
Foundation