

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

TUES. 5 DEC 1899

Date of writing Report 18 When handed in at Local Office 18

No. in Reg. Book. Survey held at Glasgow Port of Glasgow

140 on the Machinery of the Wood Iron or Steel S.S. Laimui

Tonnage Gross 504.9 Net 319.2 Vessel built at Dumbarton By whom H. Denny & Bros

Registered Horse Power 164 Engines made at do When 1884 Boilers when made (Main) 1884 (Donkey) 1884

No. of Main Boilers 4 Owners Henderson Bros (Anchor Line) Port Glasgow Voyage New York

No. of Donkey Boilers 1 If Surveyed Afloat or in Dry Dock Dry Dock

Steam Pressure in Main Boilers 160 in Donkey Boilers 80 (State name of Dock.) Govan

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. Port

Particulars of Examination and Repairs (if any) Locking

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Do. " Donkey " No

If this was not done, state for what reasons? Not due for survey

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? No To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? No To what pressure were they afterwards adjusted under steam? ✓

Has the propeller shaft been drawn and examined at this time? Yes but not examined If spare propeller shaft fitted, state whether new? ✓

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? New wood now fitted

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Completed

Examined propeller & sea cock fastenings found same in order.

When the propeller shaft was being drawn in I saw Mr Henderson Jnr. and asked him if it was their intention to keep the vessel in in class, he stated that he would inquire and if so would give us notice to examine propeller shaft! but this has not been done.

(See ship report regarding letter from Owners regarding the non-classing of this vessel).

The propeller shaft was drawn in, stern bush withdrawn and re fitted, (but not examined) propeller shaft again fitted in place and propeller secured.

General Observations, Opinion, and Recommendation:— The above is sent for the information of the Committee.

Office or Registration Fee (per Sec. 27) £ : : Fees applied for

Survey Fee (per Section 28) £ : : 18

Special Damage Fee (per Section 28) £ : : Received by me,

Travelling Expenses (if chargeable) £ : : 18

\*State if Certificate is required



*new shaft wound but not examined  
skin bush removed*

N.B. - If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation