

Glasgow

5<sup>th</sup> April 1897.

James Lewis Sennett

In view of Captain Shanks & Bell the  
Custodians, this day examining while lying off  
in the Cessnock Dock, Glasgow the new steamer  
S.S. Kawartha Moore of 10000 B.H.P. two  
days ago & with J. L. Thompson & Walker, in  
order to ascertain the extent of damage stated  
to have been caused by wood between the funnel  
and its case getting on fire on the 1<sup>st</sup>. inst  
while the vessel was off Barrow and proceeding  
on a steam trial.

If you examine the funnel & the  
whole deck the steel top of funnel habit casing  
burnt particularly near funnel and the  
caulking of the comings and goings of the wood deck  
adjoining same charred, the painting of the 26  
ft steel life boat on starboard side much blistered,  
the painting of steel casing around funnel habit  
blistered and the riveting and caulking of same  
at ports started as well as the riveting & caulking  
of casings between the life boat & ship's dock, so

Slid slightly forwardly on pool side cleared  
by the test, the painting of steel casing round  
funnel hatch between bridge and after deck  
much blistered, and a few small parts  
carrying of paint started, also the carrying  
seams of wood deck adjoining compass started,  
the painting on top plates on inside of compass  
much blistered and the painting on outside of  
coal bunkers on each side of vessel much  
blistered, observing that the coating of all  
the blistered parts is now gone much  
discoloured.

The undersigned recommended  
that the top casing plate on each side, be cut and  
removed, in fact these were long by some feet more  
widely by side 20<sup>th</sup> slide (10-3-12-6-2), and  
that the remaining parts of top of casing of funnel  
hatch be made fair again, and the plating at fore  
end of this casing and the angle bar on top be  
removed and after removal of funnel, to be  
replaced, the test marking & carrying of casing  
to make good same as required; the removal of  
top plating of funnel hatch necessitated the removal  
of four mushroom ventilators, three malleable  
bars, clear shott pipe, the top carrying frame  
to top of casing, the two front stiff and transverse  
carrying supporting of top of casing, four carrying  
clamps and bolts, two eye plates, twelve  
steps to funnel must be disconnected and

afforewards all replaced, the common webbing of  
the deck for a band thirty fathoms length be  
new laid; the 26ft steel lifeboat to be repaired  
and repainted; the lower casing of steering and a  
port side hatch removed to adm<sup>st</sup> of the deck being  
replaced as recommended by Surveyor first calling  
between bridge & hatch deck to examine existing  
fastenings and make good same as required; to  
make watertight the joint of the stanchions to bitts  
for about 10ft a length on each side, to put in  
additional fastenings to connect coming to bitts  
afterwards to fit mounting to coming on each  
side; the deck arc lighting wire on one side on  
port side under hatch laid to be tested; the  
coming between bitts & upper deck for about  
twenty five fathoms length on each side to be tested  
& reballasted; the single hatch to be tested and make  
good as required & afterwards repainted; to  
recaulk seam of hatch deck, not to exceed of the  
funnel casing and the coamings on both side  
raft to casing; the baffle plates on midship  
casing be sealed and recaulked; the coal bins  
heating on each side of vessel to be cleaned  
recaulked where coating is damaged, and the  
deck of the funnel hatch except on deck to  
be properly sealed and recaulked, ready to  
place the vessel in the same good and efficient  
condition as she was in before the damage  
occurred.

Fee £20-2-0

Ref 10% Disc



© 2021

Lloyd's Register  
Foundation