

9. No. 5674
Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office.)

FHL 6 NOV 1908

State of writing Report	When handed in at Local Office	5/11/08	Port of	GRIMSBY
in Book	Survey held at	Grimsby.	Date, First Survey	21-10
028	on the Machinery of the Wood, Iron or Steel	Sc. R. Swift	Last Survey	31-10-1908
Gross	Net	Master	(No. of Visits)	
45	45	Carleill & Co	YEAR	MONTH
116	116	By whom	When	
145	145	Engines made at	1894	9
146	146	Boilers, when made (Main)	1893	refitted 1908 (Donkey)
1	1	Owners	Port	Voyage
1	1	of Main Boilers	Guus.	Fishing.
1	1	If Donkey Boilers	(State name of Deck)	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
1	1	in Pressure		
Main Boilers	1	Main Boilers		
1	1	Donkey Boilers		

st Survey No. Port

Particulars of Examination and Repairs (if any) Pt. 1

Indicate Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the kind of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the date and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? also whether any damage report was made, and, if so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

CHARACTER, e.g. for Special Survey, Date of last Survey and of Periodical Surveys.	Years since last Survey new and expired	Machinery and Boiler Surveys (including date of N.B., if any).
+100 ft.		100 ft.
Stern Hawser		90 ft.
90 ft.		90 ft.
S.S. Guus 100 ft. 90 ft.		

Laws now changed.

No. " Donkey " " "

Is not done, state for what reasons?

what parts of the Boilers could not be thus thoroughly examined?

what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

he Surveyor examine the Safety Valves of the Main Boiler?

Yes.

To what pressure were they afterwards adjusted under steam?

100 ft.

the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

he Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Yes

, and of the Donkey Boiler?

he Surveyor examine the drain plugs of the Main Boilers?

None

, and of the Donkey Boiler?

the Surveyor examine all the mountings of the Main Boilers?

Yes

, and of the Donkey Boiler?

screw shaft now been drawn and examined?

Yes.

Is it fitted with continuous liner?

or two liners?

or is it without liners?

shaft now been changed?

No.

If so, state reasons.

shaft now fitted new?

Has it a continuous liner?

or two liners?

or is it without liners?

the distance between lignum vita of stern bush and top of after bearing of screw shaft?

A good fit.

Complete.

Survey is not complete state what arrangements have been made for its completion and what remains to be done?

The propeller shaft, propeller, stern bush (rewooded) & outside fastenings examined.

The old boiler has now been taken out of the vessel & a boiler originally fitted in the hawser 'Dark' 178 in R.P. has been placed on board. For particulars of survey repairs to this boiler see Gas. Rept 5651.

The mountings are those from the old boiler - they have been overhauled & cleaned, the main steam pipe annealed & tested to 100 ft water pressure.

General Observations, Opinion, and Recommendation:— *This machinery is*

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,07, B.M.S. 9,07, or + L.M.C. 9,07, 100 lb. 900 lb. &c.

eligible in our opinion to remain as classed with the notation + X.B. 93. refitted 1908. M.S. 792.

Note screw shaft seen 10.08.

Fee (per Section 28)	x	Fees applied for	19
Damage or Repair Fee (if any) (per Section 28)	x	Received by me,	
illing Expenses (if chargeable)	x		19

D. Mitchell & C. Marshall
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute TUES. 10 NOV 1908

signed + R.B. 93 M.
refitted 08



LLC
RE
AN

Bolter taken from the s/s "Dart"
has now been fitted on board

F.R.-If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side.

This Vessel
It is submitted that
this vessel is eligible for
THE RECORD + N.B. 93.

Refitted 10.08.

160t.

John Smith

\$10.08

GMS358/123



© 2018

Lloyd's Register
Foundation