

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

30 SEP 1929

of writing Report	23rd Sept. 1929	When handed in at Local Office	25 th Sept. 1929	Port of Gothenburg
in Book.	Survey held at	Gothenburg	Date, First Survey	25 th March 1929
26	on the Machinery of the	Wood, Iron or Steel Twin S. "SOLGLIMT" (Stockholm)	Last Survey	10 th Sept. 1929
Gross	19279	(No. of Visits)	14	
Net	7123			
Final Power	1355			
Main Boilers	3DB			
Donkey Boilers	None	Owners' Address		
Pressure	906 lbs	(If not already recorded in Appendix to Register Book).		
Donkey Boilers	v	Port	Haugesund	
		Voyage		
		Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).		
		CHARACTER.		
		For Special Survey		
		Data of last Survey and of Periodical Surveys		
		Local Standard Surveyed, expired.		
		Machinery and Boiler Surveys (including date of N.B., if any).		
		L4C		
		4.5.1.28		
		B.S. 8.2.28		
		7.2.28		
		5.5 Got 2nd 1.3-4.2.28	CL 1.28.	
		5.5 Got 1.1-28		
		FITTED FOR OIL FUEL 3.22		
		N.P. ABOVE 100° F		

Report No. Port

Particulars of Examination and Repairs (if any) Alterations

ideal Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and the initials of any letters respecting this case.

In case where the Surveyor has not made a special damage report he is required to state whether he tendered his services for this purpose, and why they were declined?

damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Donkey "

was not done, state for what reasons?

at parts of the Boilers could not be thus thoroughly examined?

at special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Surveyor examine the Safety Valves of the Main Boiler?

Yes

To what pressure were they afterwards adjusted under steam?

906 lbs.

Surveyor examine the Safety Valves of Donkey Boiler?

v

To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Yes

, and of the Donkey Boiler?

Surveyor examine the drain plugs of the Main Boilers?

None fitted

, and of the Donkey Boiler?

Surveyor examine all the mountings of the Main Boilers?

Yes

, and of the Donkey Boiler?

new shaft now been drawn and examined? No

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated?

shaft now been changed? No If so, state reasons

shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated?

distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft?

3 in.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done?

Complete

The propellers, sea connections and their fastenings examined.

The boilers examined internally with safety valves and mountings.

Repairs effected due to wear & tear:

A few leaky seams in combustion chambers of the double-ended boilers made tight by means of electric welding.

12 ordinary tubes in the after centre tube nest of the starboard double ended boiler removed.

5 ordinary tubes in the port after tube nest of the port centre double ended boiler removed.

The mountings of all boilers overhauled and placed in order.

White metal on the HP ahead guide shoe of port main engine renewed.

P.T.O.
al Observations, Opinion, and Recommendation:— The Machinery of this vessel clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9.11, B.M.S. 9.11, or L.M.C. 9.11, 140 lb., F.D., &c.)

eligible in our opinion to remain as now classed in the Register with fresh record of B.S. 9.29.

Actions
age or Repair Fee (if any)
or Section 40
total oil boilers
expenses (if chargeable)

Rs 285.00
Rs 995.00
Rs 1934.50
Rs 1653.20

Fees applied for
27 July 1929

Received by me,
22/10/1929

E. Bernelinus

Engineer Surveyor to Lloyd's Register of Shipping.

for application for 24th July 1929 Received 5th Aug. 1929


FRI. 3 OCT 1930

FRI. 21 NOV 1930

tee's Minute TUE. 15 OCT 1929

G.S. 9.29

Amend part 1st
+ N.W.



Alterations in connection with vessel being converted to a floating whale oil factory.

The port single-ended and port double-ended boilers removed from the vessel.

30 whale oil boilers, manufactured by Messrs H.B. Nydqvist & Holm, Stockholm, under our supervision & as per plan N° 28918 approved on the 4th February 1929, have been placed on board.

6 Hartmann Apparatus and 3 evaporators (total capacity 150 tons/24 hours) have been fitted on board. All boats under hatches See Yul Ats 4/10/33 attached to Ham Rep't 20894

The pumping arrangement has been altered in accordance with plan N° 59318 A forwarded you under separate cover.

Draining of C-dish arranged as per plans N° 60609 & 60520, approved on the 8th August 1929.

Heating coils have been fitted all over the bottom of the whale oil tanks forward of the machinery space and around suction in whale oil tanks astern of the machinery space. These coils have been tested with water pressure to 20 kg/cm² after being fitted on board.

The exhaust drains of same led to an observation tank placed at forward part of the Engine room. (Reduced steam pressure of 120 kg/cm² to be used for same.)

The port steam engine driven electric generator removed from the vessel.

Two steam engine driven generators, manufactured by Messrs H.H. Adlard Son, Co. Ltd of Bedford. Cylinder diam of same 11¹/₂ 25" and stroke 7" placed on board. For further particulars please 1st entry report of Electric installation.

As due 8.29 held
Port boilers removed
from the vessel

Scraping oil heating arrangements
filled as approved & 36 oil tanks fitted.

It is understood
that this vessel is classed
THE RECORD.

S. J. G. J.

Amount burnt since a
follows: 1 DOB 258
24 c.t. 11.207 K.S. 17310
11/15 VIII

J. B. J.
11/15 1929



© 2021

Lloyd's Register
Foundation