

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report July 18th 1900 When handed in at Local Office 17th July 1900 Part of WEST HARTLEPOOL
 No. in Reg. Book. Survey held at West Hartlepool Date, first Survey 19th May Last Survey July 13th 1900
120 on the Machinery of the Wood, Iron or Steel S. S. Malaga Master M. Rees - 96
 Tonnage { Gross 1614 Net 1024 Vessel built at Hartlepool By whom N. Gray & Co. When 1876 Boilers, when made (Main) 1900 (Donkey) 1900
 Registered Horse Power 160 Engines made at Stockton Owners Ball & Co. Port London Voyage London
 No. of Main Boilers 2 If Surveyed Afloat or in Dry Dock Gray's Dry Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 No. of Donkey Boilers 2 Steam Pressure in Main Boilers 80 lbs. in Donkey Boilers 80 lbs.

Last Survey No. Port

Particulars of Examination and Repairs (if any) M. S. Allen Boilers

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam? 84 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam? 80 lbs

Has the propeller shaft been drawn and examined at this time?

If spare propeller shaft fitted, state whether new?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Vessel placed in dry dock, propeller shaft drawn exam. & found in good condition. New propeller & Injection valve fitted. Sea cocks & valves and sea cock fastenings good.

Exam. Cyl. pistons, valves, crank thrust & tunnel shafting, condensers & all pumps. — Both Cyls. sent to Works, L.P. Cyl. bored out, new liner fitted & dia. reduced to 58 $\frac{1}{2}$ ". Pistons &c. turned to suit. Valve spindles, piston rods, & air pump rod turned up in lathe, glands rebushed & new neck rings fitted. Crank shaft lifted & rebuffed, & shafting lined up throughout. All main steam pipes, including two new ones, annealed & afterwards tested by high press. to 200 lbs & found tight. Dia. of crank shaft 11". Tunnel shafting 10 $\frac{1}{4}$ " & propeller shaft 10 $\frac{1}{4}$ ".

Boilers. — New Main & donkey boilers fitted, see Attached Report.

General Observations, Opinion, and Recommendation: — The Machinery of this vessel is now

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9, 97, B.&M.S. 9, 97 or L.M.C. 9, 97, 140 lb., F.D., &c.)

in good condition, & eligible in our opinion to remain as classed and to have record L.M.C. 4, 00, also N.B. 4, 00, N.D.B. 1000 and dia. of L.P. Cyl 58 $\frac{1}{2}$ " marked in the Register Book. likewise Main & donkey boiler pressures. 80 lbs. N.H.P. 160

Office or Registration Fee (per Sec. 27)..... £

Survey Fee (per Section 28)..... £

Special Damage Fee (per Section 29)..... £

Travelling Expenses (if chargeable)..... £

State if Certificate is required

Fees applied for

17. 7. 1900

Received by me

19. 7. 1900

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

FRI. 20 JUL 1900

Assigned

+ L.M.C. 4, 00

+ N.B. 4, 00 N.D.B. 1000

HPL 389-0193

Lloyd's Register
Foundation

Screwshaft examined: Sternbush reported.

ed. Cylinders bored out.
Men name & donkey bolts filled

It is submitted that
this vessel is eligible for
THE RECORD.

not at all. LMC 7.00 and
NB 7.00, NBS
or working pressures 80 lb,
diameter of Cylinders
58 3/4, and reams of
74 1/2; preke surface
etc as per attached
report.

CM.
18.7.00



© 2020

Lloyd's Register
Foundation

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.