

the clenchwork in all cases in breadth at least five times the diameter of the rivets in double rivetted
 e times the diameter of the rivets where single rivetting is admitted? Yes
 butts lay close together throughout their length without requiring any making good of deficiencies? Yes
 fill in solid with single pieces, or are they in short lengths of various thicknesses? Filled in solid
 ning pieces, or plate to plate, &c., conform well to each other? Yes and are the rivet holes
 in the outer plate? Yes
 or have been put through the seams or butts of the plating? a few 3581 Iron

condition, and sufficient in size and length.
Murray, Weeks & Harbour Board
CABLES, &c.

	Fathoms.	Inches.	ANCHORS, and their weights.	
			N ^o .	Weight.
<i>Testing Department</i> Laid to <i>Sea</i> <u>64</u> " <u>12</u> " <u>2</u>	150	1 5/16		
Chain <i>Sea</i> <u>64</u> " <u>12</u> " <u>2</u>	150	1 5/16	Bower,	—
Hempen Stream Cable	—	—	Stream,	—
Hawser	—	—	Kedge,	—
Towlines	—	—		
Warp	—	—		
All of _____ quality.				

Her Standing and Running Rigging _____ sufficient in size and _____ in quality.

She has _____ Long Boat and _____

The present state of the Windlass is Good Capstan Good and Rudder Good Pumps lead metal good

General Remarks, Statement and Date of Repairs, extent of corrosion (if any) both internally and externally, and condition of rivets.

DATES of Surveys held while building, as per Section 17.	1st. On the several parts of the frame, when in place, and before the plating was wrought	2nd. On the plating during the progress of rivetting	3rd. When the beams were in and fastened, and before the decks were laid	4th. When the ship was complete, and before the plating was finally coated	5th. After the ship was launched
	<u>July 14th 1863</u>	<u>August 20th "</u>	<u>July 14th "</u>	<u>Jan'y 12th 1864</u>	<u>March 14th "</u>

This vessel has an Interstitial keelson about midway between the middle line keelson and the bilge plates $\frac{1}{16}$ Angle Irons $5\frac{1}{2} \times 4\frac{1}{2} \times \frac{9}{16}$ In. on top of floor, Orlop beams bulb Iron $8\frac{1}{2} \times 9\frac{1}{16}$ In. Angle Irons on top $3\frac{1}{4} \times 3\frac{1}{4} \times \frac{9}{16}$ In beams rivetted to every fourth, and eighth frame alternately, and a knee plate between in all wide spaces. Stinger plates $24 \times \frac{1}{16}$ In. Iron angle Irons $4 \times 3 \times \frac{9}{16}$ In. rivetted back to back on each of hatchways for 16 feet runs ships, diagonal tie plates, abaft of each mast $13\frac{1}{2} \times \frac{1}{16}$ In rivetted to upper and lower deck beams

The Iron in this vessel is good, but the workmanship is rough.

In what manner are the surfaces preserved from oxidation? The flat of bottom to round the turn of bilge is Portland Cement above this together with the entire outside of hull, is coated three, with a mixture of Red & White lead

I am of opinion this Vessel should be classed 12 A

The amount of the Fee £ 5 : 0 : 0 is received by me, Wm. Linton

Special £ 41 : 14 : 6

Travelling Expenses £ 18 : 6 : 6

Certificate (if required) Lyb " 14 " b

Committee's Minute 13th May 1864

Character assigned. A - for 12 Years - say A

