



22874

Iron

lifted and repaired, the ship strengthened, and the mast shortened  
 about six feet, three new tops, partly new ~~lower~~ lower rigging, new  
 new blocks and running rigging, an entirely new suite of sails  
 Main Deck has had six new shaves on Starboard side, and eighteen  
 new shaves on Port side, Top Deck has had several new shaves on  
 Starboard side, and two new shaves on Port side, all to their original  
 shifts, chain Deck houses had been repaired, and Top Deck house  
 has been rebuilt, chain & Top sails had been made good with best  
 Topgal Bulwarks had been made good, and a Board, and Board  
 damaged, two each been replaced with a new one, Main Deck has  
 been caulked all over, and the Bussel has been doctored, bottom examined  
 and found to be uninjured and good and has been recoated  
 All other less important repairs had also been done

*J. V. C. RIVAZ*  
*Surveyor*  
*Superintendent of Shipping*

J. V. C. RIVAZ  
 THE COMMERCIAL UNION AS  
 Esq.,  
 SURANCE COMPANY,  
 38 & 40, Cross Street,



© 2019

Lloyd's Register  
 Foundation