

REPORT of SURVEY for REPAIRS, &c.

No. 15123

No. in Survey held at *South Shields* Date, first Survey *6 Sept.* Last Survey *9 Sept.* 188*0*
 Reg. Book.

on the *Scw. "H. J. Pallison"* Master *C. Hansen*

TONNAGE under Tonnage Deck *746*
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage *1138*
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm. *721*
 Built at *Copenhagen* When built *1877*
 Owners *Pallison & Co* Port belonging to *Copenhagen*
 Residence *Copenhagen*
 By whom built *Burmeister* Destined Voyage *Chalapa*
 If Surveyed Afloat or in Dry Dock *H. J. Rawards & Toms Dock*
 (State Name of Dock)


Length of Poop *ft.* Ditto, Forecastle *ft.* Ditto, Raised Quarter Deck *ft.* Years assigned. *100 A 1*
 Character in Register Book. *12-49*

Last Survey, No. *25213* Port *Crane*
 REPAIRS, OR EXAMINATION AS PER RULE *Annual Survey*

Cause of Repairs to be clearly stated.

On sighting the bottom &c of this vessel a slight defect was observed at the lip, or thin end of the weld connecting the Rudder Post to the Propeller frame at the keel, and which has now been additionally secured with a forged knee plate on each side of the frame as per sketch.

Now done, The bottom sighted and cleaned down; the outer surface of shell plating coated with 2 coats of Rabitzens Patent composition up to about 14' 6"



Present Condition of the		Decks		Breasthooks and Stemson		Windlass and Capstan	
Waterways	<i>Good</i>	Transoms, Pointers, and Crutches	<i>Good</i>	Pumps	<i>Metal</i>	Boats	<i>Good</i>
Comings	<i>"</i>	Timbers of the Frame at the openings	<i>Good</i>	Masts, Yards, &c.	<i>In where practicable</i>	Condition, how ascertained	<i>Good</i>
Upper Deck Beams & Fastenings	<i>"</i>	Ditto Ditto at other places	<i>"</i>	Sails	<i>Good</i>		<i>Good</i>
Lower Deck Beams & Fastenings	<i>"</i>	Keelsons	<i>"</i>	Anchors	<i>No. of 3R. 15. 2H.</i>		<i>Good</i>
Planksheers	<i>"</i>	Clamps and Shells	<i>"</i>	Cables	<i>Not seen</i>		<i>Sufficient</i>
Sheerstrakes	<i>"</i>	Ceiling	<i>"</i>	Hawsers and Warps			<i>Sufficient</i>
Topsides	<i>"</i>	Rudder	<i>"</i>	Standing & Running Rigging			<i>Sufficient</i>
Wales	<i>"</i>	Caulking of	<i>"</i>				<i>Sufficient</i>
Plank (Bottom) and Counter	<i>"</i>	Bottom, Deck, & Waterways	<i>Good</i>				<i>Sufficient</i>
Engine Room Skylights	<i>good</i>	Coal Bunker, Openings, Lids, &c.	<i>good</i>	Scuppers	<i>good</i>	Cargo and Main Hatchways	<i>good</i>
Hatches	<i>good</i>						<i>good</i>

General Observations, Opinion as to Class, &c.
This vessel is now in good and efficient condition and eligible in my opinion to remain as classed

The Amount of Entry Fee ... £ *2* : *2* : *0* received by me, *James Gibson*
 Special ... £ *2* : *2* : *0* 1880
 Certificate (if required) to be sent as per margin... £ *—* : *—* : *—*

(Travelling Expenses, if any, £ *—* : *—* : *—*)
 Committee's Minute *Friday, December 3rd. 1880.*

Character assigned *100 A*
 Lloyd's Register Foundation

Surveys are requested not to write on or below the space for Committee's Minute.

IRON 17-0098