

No. 1184 Survey held at Jersey Date 22/10/84 September 7th to 10th 1884
 on the SS L.AURA Master John Bond
 Tonnage Old Built at Grey, Jersey When built 1863 Launched Sept 3rd
 By whom built John Bond Owners Whitely & Co.
 Port belonging to Jersey Destined Voyage Fishing & Boasting
 Surveyed while Building, Afloat, or in Dry Dock While Building

Length aloft	Foot		Inches		Extreme Breadth Outside	Foot		Inches		Depth of Hold	Foot		Inches	
	50	50	10	10		15	15	4	4		4	4		
Scantlings of Timber.														
TIMBER AND SPACE	14 1/2 inches				Garboard Strakes	2				Limber Strakes	2 1/4			
Floors	6 8				Garboard to Bilge	2				Bilge Planks	2 1/2			
1st Foothooks	5 1/2				Bilge Planks	3				Ceiling in Flat	1 1/2			
2nd Ditto	5 1/2				Bilge to Wales	2				Ditto Bilge to Clamp	1 1/2			
3rd Ditto	5 1/4		3 1/4		Wales	2 1/4				Hold Beam Clamps				
Top Timbers	5 1/4		3 1/4		Topsides	2				Deck Beam Ditto	2 1/2			
Deck Beams	3 1/4		3		Sheer Strakes	2				Ceiling 'twixt Decks	1 1/2			
Deck Beams, length amidships	14 1/8				Plank Sheers	2				Hold Beam Shelves				
Hold Beams					Water Ways					Deck Beam Ditto	1 1/2 x 3 1/2			
Hold Beams, length amidships					Upper Deck									
Keel	4 1/2		11		Lower Deck									
Scarphs of Ditto	the length				Ditto, faying surface against Timbers									
Keelsons	8		9		Upper Deck	2 1/4								
Scarphs of Ditto	5 1/4													

Size of Bolts in Fastenings, distinguishing whether Copper, Yellow Metal, or Iron; also of Treenails.

	Copper or Y.M. in Ship.	Iron in Ship.	Inches required per Rule		Copper or Y.M. in Ship.	Iron in Ship.	Inches required per Rule
Heel-Knee, & Deadw'd abaft		1		Transoms and throats of Hooks		1/6	
Scarphs of Keel, N°				Arms of Hooks		1/6	
Keelson Bolts through Keel at each Floor	1/8			Thro' Bilge & Limber Strakes	1/2		
Bolts thro' Heels of Timbers against Deadwood	5/8			Thickstuff over Double Floors			
				Butt End Bolts	1/2		
				Pintles of the Rudder	1 1/2	1/4	
				Hold Beam Bolts in			
				Waterway			
				Knees			
				Shelf or Clamp			
				Deck Beam Bolts in			
				Waterway			
				Knees			5/8
				Shelf or Clamp			5/8
				Nails or Bolts in Flat of Deck			1/2
				Treenails			1 inch

Timbering.—The Space between the Floor Timbers and Lower Foothooks is 5 Inches. The Space between the Top-Timbers is 5 Inches.
 The Floors consist of Jersey oak The First Foothooks of Jersey oak
 The Second Foothooks of Jersey oak The Third Foothooks and Top Timbers of Jersey oak
 The Shifts of the First and Second Foothooks are not less than one inch N. B. When less than prescribed by the Rule, state how many.
 The rest of the Shifts of the Frame are one
 The Frame is not squared from the First Foothook Heads upwards, and is free from sap, and from thence downwards, the frame is well squared
 The all Frames are all bolted together to the Gunwale. N. B. If not, state how bolted.
 The Butts of the Timbers are close together; their thickness not less than full of the entire moulding at that place.
 The Frame is chocked with butt at each end of the chock. The Main piece of Rudder is the oak of Windlass is the oak
 The Keel is one The Main Keelson is oak & 2nd oak and is free from all defects.
 The Stem, and Stern Post of oak The Transoms, Knight Heads, Hawse Timbers, and Aprons of oak Deadwood, of oak and are is free from all defects.
 The Deck and Hold Beams of oak The Breasthooks of oak The Knees of oak

Planking Outside.—From the Keel to the Height defined in Note to Table A } the Plank is oak
 or to the First Foothook Heads }
 From the above named Height to the Light Water Mark oak
 From the Light Water Mark to the Wales oak
 The Wales and Black-strakes are oak The Topsides & Sheer-strakes oak
 The Spirketting and Plank-sheers oak The Water-ways { Upper Deck oak
 Lower Deck oak
 The Decks oak State of good

The Shifts of the Planking are not less than 5 Feet 5 Inches. N. B. If less than prescribed by the Rule, state whether general or partial, and if partial, in what part of the Ship. The Planking is wrought smooth between, and without step-butting.
Planking Inside.—The Limber-strakes and Bilge-strakes are oak
 The Ceiling, Lower Hold, and between Decks oak Shelf Pieces and Clamps oak
Fastenings.—To Hold Beams oak

Deck Beams oak
 Number of Breasthooks one Pointers one Crutches one
 End Bolts are of copper in the Bottom: one Bolts in each Butt End one through and clenched.
 Limber Strakes oak bolted through and clenched. Treenails of oak How Made oak
 Thickstuff over Double Floors oak bolted through and clenched. General Quality of Workmanship good

We certify that the above is a correct description of the several particulars therein given

Owner's Signature J. F. Wood Surveyor's Signature Wm. J. Wood

SER 54-0343

Her Masts, Yards, &c. are in Good condition, and sufficient in size and length.

She has SAILS.		CABLES, &c.		ANCHORS, and their weights.		
N ^o .		Proof Tons.	Fathoms. Inches.	Proof Tons.	N ^o .	Weight.
<u>1000</u>	Fore Sails,	Chain	11 1/16	Bower,	1	1.3.8
<u>and</u>	Fore Top Sails,	Hempen Stream Cable	80 5	Stream,	1	1.1.7
<u>Share</u>	Fore Topmast Stay Sails,	Hawser				
<u>as</u>	Main Sails,	Towlines				
<u>usual</u>	Main Top Sails,	Warp ^s	80 2 1/2	Kedge,		2-15
and		All of <u>Good</u> quality.				

Her Standing and Running Rigging Shrub Wire Stay sufficient in size and Good in quality.

She has no Long Boat and See Letter annexed

The present state of the Windlass is Good Capstan Shrub Wire Rudder and Pumps Good

General Remarks and Statement and Date of Repairs, if any.

DATES of Surveys held while building, as per Section 35.	1st. When the Frame is completed	2nd. When the Beams are put in, &c.	3rd. { When completed, and before the plank be painted or payed }
	<u>June 3rd 1864</u>	<u>" 22 1864</u>	<u>August 1864.</u>

* Paint under Special Survey
Pieces taken out of Bottom Planking to test Caulking -
Anchor & Chain tested at the Machine belonging to
the Jersey Mutual Insurance Society, and certificates
produced - A. J. Syrett

N.B. After launching, but before the above report was signed by the Builder, this vessel, was on the 4th September, run into by H.M.S. "Speedy" whilst lying at the Pier in Gray Harbour - and received the following damage - The Plank on outside, below the Beams - on Starboard side broken, and many Treennails started, the Strancher broken, piece of Wash Strake Borr Rail, and Bulwarks, broken split, and carried away - Also Working Chock forward - On Port Side the vessel appeared strained and many Treennails started - Sixteen Strakes of Deck more or less injured by being cut by the Mastings (Iron) of the Steamer - Inside - found the Shelf Piece on Port Side slightly started, and several Strakes of Ceiling dislodged apparently by the forcing inwards of the heels of short Lgh Timbers - On Starboard Side - The Clamp and one length of Ceiling Plank slightly sprung - In consequence of the above - Mr. the undersigned, came, at the request of the Commander of the Steamer, surveyed the damage and supervised the repairs thereof, the following materials having been made use of - viz - 395 ft of Deck Plank - 56 feet of Ceiling - 24 feet of Clamp - 30 ft outside Plank below Beams, one Strancher - Borr Rail & Chock renewed - also 30 ft Wash Strake and 30 feet Borr Bulwark - About 250 Treennails driven, and 80 additional Copper Through bolts introduced - It was considered vessel was most strained from effects of the blow -

The vessel is now in good condition, and in every way eligible for the Class originally intended - A. J. Syrett - I. F. Vicat

Present condition of Caulking of Bottom, Good Deck, Good and Waterways

If Sheathed, Doubled, Felted, or Coppered _____ When last done _____

I am of opinion this Vessel should be Classed P. A. 1

The Amount of the Fee.....£1 : : is received by me, A. J. Syrett

extra Special£4 : 4 : -
 Special£3 : 3 : -
 Certificate£ : : -

Committee's Minute 25th October 1864

Character assigned A 4 for 8 Years M.A.D.
 (A & C. P.)

