

No. 492 Survey held at Pondowat Date 12 June 1835 492
 on the Bark Ocean Master Murwick
 Tonnage 270 Built at Whitty When built 1797 P.D.
 By whom built Owners Soines
 Port belonging to London Destined Voyage North America
 If Surveyed Afloat or in Dry Dock Afloat

Length aloft.....	Feet.	Inches.	Extreme Breadth	Feet.	Inches.	Depth of Hold	Feet.	Inches.
Scantlings of Timber.								
Timber and Space.....	each		Moulded	inches	inches	inches	Outside.	Inside.
Floors.....	sided			Middle	Ends		Keel to Bilge	Foot Waling
1 st Foothooks.....	"	"		"	"		Bilge Planks	Bilge Planks
2 nd Ditto.....	"	"		"	"		Bilge to Wales	Ceiling in Flat
3 rd Ditto.....	"	"		"	"		Wales	Ditto Bilge to Clamp
Top Timbers	"	9		3½			Topsides	Hold Beam Clamps
Deck Beams	"	11		10			Sheer Strakes	Deck Beam Ditto
Hold Beams	"	12		11½			Plank Sheers	Ceiling 'twixt Decks
Keel	"	14		18			Water-ways	Hold Beam Shelves
Kelsons	"						Upper Deck	Deck Beam ditto

Thickness of Plank.

Outside.	inches.	Inside.	inches.
Keel to Bilge		Foot Waling	
Bilge Planks	3	Bilge Planks	4
Bilge to Wales		Ceiling in Flat	2½
Wales		Ditto Bilge to Clamp	3
Topsides		Hold Beam Clamps	4
Sheer Strakes		Deck Beam Ditto	3
Plank Sheers	3	Ceiling 'twixt Decks	2½
Water-ways	5	Hold Beam Shelves	3½
Upper Deck	3	Deck Beam ditto	

Size of Bolts in Fastenings.

Copper.

	inches
Heel-Knee, and Dead Wood abaft	
Scarps of Keel.....	N.
Floor Timber Bolts.....	Paper
Kelson ditto.....	Leather
Transoms and throats of Hooks	
Arms of Hooks	

Iron.

Iron.

	inches.
Hold Beam	
Deck Beam	
same in Iron above the Copper	{

Timbering.—The Space between the Floor Timbers and Lower Foothooks in this Vessel is _____ Inches. The Space between the Top-timbers is 3½ Inches. The Stem, Stern Post, Transoms, Aprons, Knight Heads, Hawse Timbers, are composed of English oak and are not free from all defects.

Her Floors and first Foothooks are composed of _____

Timber.

Her other Foothooks and Top Timbers of English oak

Her Shifts of the first and second Foothooks are not less than _____ N.B. When reported by you less than the prescribed Rule, then state how many.

The rest of the Shifts of the Frame are _____

The Frame is sufficiently squared from the first Foothook Heads upwards, and _____ free from sap, and from thence downwards, the frame is _____

The alternate Frames are _____ bolted together.

The Butts of the Timbers are _____ close together; their thickness not less than _____ of the entire moulding at that place.

The Frame is _____ chocked with _____ Butt at each end of the chock.

The Main Kelson is composed of English oak and the False Kelson of _____

The Scarps of the Kelsons are not less than 4 feet 6 inches.

The Deck and Hold Beams are composed of _____

Planking Outside.—This Vessel's Plank from the Keel to the first Foothook Heads is composed of _____

From the first Foothook Heads to the Light Water Mark of _____

From the Light Water Mark to the Wales of _____

The Wales and Black-strakes are of _____

The Topsides of _____

English & Foreign Oak mixed

The Sheer-strakes of English oak

Water-ways of America

The Shifts of the Planking are not less than one regular aft N.B. If reported less than the prescribed Rule, state whether general or partial, and if partial, in what part of the ship. Some 2 & some 3 eleven

Planking Inside.—The Clamps are composed of English oak the Stringers of _____

The Bilge Planks of English oak and the remainder of the Ceiling of the same

Fastenings.—To Hold Beams 2 Woodlocking and one Iron hanging knees

Deck Beams 2 do 18 & few Iron hanging knees

Number of Breasthooks _____

Pointers _____

Crutches _____

Butts End Bolts are of Copper in the Bottom, and the Bolt in each Butt End through and clenched.

Bilge and Footwaling Copper bolted through and clenched.

General Quality of Workmanship has been middling

We certify that the preceding is a correct description of the above-named Vessel.

Builder's Name

Surveyor's Name

1492 Son

Her Masts, Yards, &c. are in good condition, and sufficient in size and length.

She has SAILS.

Nº.
2 Fore Sails,
2 Fore Top Sails,
2 Fore Topmast Stay Sails,
1 Main Sails,
2 Main Top Sails,
and

CABLES, &c.

Fathoms.		Inches.	Nº.
210	Chain		3 Bower,
120	Hempen Stream Cable.....	7	1 Stream,
100	Hawser	5½	1 Kedge,
	Towlines		All of proper weight.
90	Warp	4	
	All of <u>good</u> quality.		

ANCHORS.

3 Bower,
1 Stream,
1 Kedge,
All of proper weight.

Her Standing and Running Rigging is _____ sufficient in size and good in quality.She has One Long Boat and One SkiffThe present state of the Windlass is good Capstan _____ and Rudder good**General Remarks—Statement and Date of Repairs.**

The ceiling below the clamps and about the bows is generally in a bad state the Apron ~~and~~ lower breast work forward hold beam and its knees and many of the timbers expose through the broken places in the ceiling are defective it is evident from her appearance generally that her timbering is defective to a considerable extent her topsides are also bad in many places walls are unfair condition the bottom is doubled

Repairs 1835. Part new walls 2 new Hold Beams and the fastening of the Hold Beam knees generally renewed the new upper bulk beam several others clamped

If Sheathed, Doubled, or Felted, Doubled & Feltedand Date when last done 1830And I am of opinion this Vessel should be Classed IIThe Amount of the Fee.....£ 1:1:0 is received by me, John SmithCommittee Minute 11 June 1835Character assigned I 1 J SThos McPhie Peck SmithJohn Smith