

41783

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Received at London Office, 12/9/82)

No. in Reg. Book. 537 Survey held at London Date, first Survey 17. Aug Last Survey 17. Aug 1882

on the Machinery of the S. S. "Huntingdon" (Number of Visits 1)

Tonnage, Gross 2224 Built at Newcastle When built 1881

Ditto, Net 1463 Owners W. Milburn & Co Port belonging to London

Diameter of Cylinder 36 68 Engines made by R & W Hawthorn When made 1881

Length of Stroke 42 Boilers made by _____ When made 1881

Pressure of Steam 80

Registered Horse Power 275 If Surveyed Afloat or in Dry Dock James Ligon Wks Classed 100A1

Last Survey No. 41685 Port London 85. 82
+ L.M.C. 4. 81

Particulars of Repairs and Examination Damage to Piston.
(State cause of Repairs.)

The low pressure piston and piston rings had broken in two at sea and had been repaired. A new piston & rings have been fitted to the piston rod.

Examined sea-cocks & connections and found them in a good condition.

General Observations, Opinion, and Recommendation:— As far as seen the machinery of this vessel appears to be in a safe working condition and is in my opinion eligible to remain as classed.

Damage £ 2. 2. -

Entry or Registering Fee... £ : :
Survey Fee (per Section 28) ... £ : : received by me,
Certificate (if required) ... £ : : 188
to be sent as per margin.

(Travelling Expenses, if any, £ _____)

C. E. Browne
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Friday, 22nd September, 1882

Assigned J. B. W. Remain as Classed



Form No. 9-3000, 25/1/81. (The Surveyors are requested not to write on or below the space for Committee's Minute.) (Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.) (State if Report is also sent on the Hull of the Ship.) (Insert Character precisely as in the Register Book.)

L700-699207

His submitted that this
asset is eligible to remain
as closed

RM 9/9/82

[Faint, illegible handwritten notes in cursive script, likely bleed-through from the reverse side of the page.]



© 2021

Lloyd's Register
Foundation