

# Report of Survey for Repairs, &c., of Engines & Boilers.

48413  
THURS 10 AUGUST 1888  
(Received at London Office,)

No. \_\_\_\_\_ Date of Writing Report August 14<sup>th</sup> 1888 Port of London  
 No. in Reg. Book. 799 Survey held at London Date, first Survey August 10<sup>th</sup> Last Survey August 14<sup>th</sup> 1888  
 on the Machinery of the S.S. Miranda Master A. Keys No. of Visits \_\_\_\_\_  
 Tonnage { Gross 996 Vessel built at Newcastle By whom Palmer & Co When 1865 3  
 { Net 736 Engines made at Newcastle When 1871 Boilers, when made (Main) 1871 (Donkey) 1884  
 Registered Horse Power 140 Owners J. Fenwick Sons Port London Voyage \_\_\_\_\_  
 No. of Main Boilers 1 If Surveyed Afloat or in Dry Dock Dry Dock Class of Vessel & Machinery 60A1-12-87  
 Steam Pressure in Main Boilers 45 lbs (State name of Dock.) \_\_\_\_\_ (As in Register Book.) B.M.S. 7-87  
 in Donkey Boiler 80 lbs

Last Survey No. \_\_\_\_\_ Port \_\_\_\_\_

Particulars of Examination and Repairs (if any)  
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time?  
 If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler? } This vessel being in London Dock  
dry dock examined sea connections & propeller fastenings & found them satisfactory  
Examined also main boiler & safety valves & superheater & with the exception of some slight leakages on shell found them in good condition.  
This caulking has now been executed also sundry slight repairs to engines have been done  
Donkey boiler is comparatively new & is marked No 2326  
Lloyds test 160 lbs □" W.S. 6.9.87

Main boiler safety valves are weighted lever valves & calculated to blow at 45 lbs per sq inch

General Observations, Opinion, and Recommendation:-- The machinery of this vessel as far as seen is in good order & she is eligible in my opinion to remain classed & have the notification B.S. 8-88 recorded in the Register Book  
 (State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey.)

Office or Registration Fee (per Sec. 27).....	£ : :	Fees applied for 20.5.1888 received by me, 23/8.1888
Survey Fee (per Section 28) .....	£ 2 : 2 :	
Special Damage, Fee (per Section 28) .....	£ : :	
*Certificate (if required) as per margin .....	£ : :	
Travelling Expenses (if chargeable).....	£ : :	

Maurice Wilson  
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute TUES 21 AUGUST 1888  
 Assigned B S 8/88



Lloyd's Register of Shipping and Machinery precisely as in the Register Book

It is submitted that  
this vessel is eligible to  
have B.S. 8.88 recorded

MD

21.8.88

*[Faint, illegible handwritten text, likely bleed-through from the reverse side of the page.]*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2021

Lloyd's Register  
Foundation