

Report of Survey for Repairs, &c., of Engines & Boilers.

No. 154 Date of Writing Report August 13th 1888 Port of London (Received at London Office, 1888 14 AUGUST 1888)
 No. in Reg. Book. 154 Survey held at London Date, first Survey August 7th Last Survey August 13th 1888
 on the Machinery of the S.S. Samuel Lang Master White No. of Visits 4
 Tonnage { Gross 623 Net 394 Vessel built at Palmer By whom Palmer Bros When 1854
 Registered Horse Power 40 Engines made at J. Stewart When 1875 Boilers, when made (Main) 1873 (Donkey) None
 No. of Main Boilers 1 Owners J. Howard & Sons Port London Voyage
 Steam Pressure in Main Boilers 45 lbs If Surveyed Afloat or in Dry Dock Dry Dock Class of Vessel & Machinery SOA1-6-87
 in Donkey Boiler ✓ (State name of Dock.) (As in Register Book.) MS. 4.85

Last Survey No. Port

Particulars of Examination and Repairs (if any)

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time?

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler? This vessel being in London
Dry Dock examined propeller fastenings, & sea cocks & connections
& found them in good order, tail shaft down to full

Examined cylinders, pistons, slide valves, steam chests, air, & condenser
feed & bilge pumps also crank & thrust shafting & found
them satisfactory, some dry small repairs have been done
to machinery

Examined main boiler & safety valves (weighted level) also
superheater, & found plates in two places in superheater
rather thin & pitting, also several stays corroded, & joints
in combustion chamber leaking

Doubling plates have been placed over the affected parts
in superheater, new stays fitted where corroded, & joints
in comb chambers caulked & where necessary new rivets put
in

Safety valves weighted by calculation to 45 lbs per
sq inch

General Observations, Opinion, and Recommendation:-- Eligible in my opinion
 (State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey.)
to be classed MS. 8. 88 in the Register Book, the machinery
being now in good order.

Office or Registration Fee (per Sec. 27).....	£ : :	Fees applied for
Survey Fee (per Section 28)	£ 3 : 3	40. 8 188 8
Special Damage, Fee (per Section 28)	£ : :	
*Certificate (if required) as per margin	£ : :	received by me,
Travelling Expenses (if chargeable).....	£ : :	23. 8 188 8

Maurice Putson
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute TUES 21 AUGUST 1888
 Assigned B & M 8 1888

It is submitted that
This vessel is eligible to
have B.Y.M.S. S.S. 88
Recorded.

MA

20. 8. 88